

Basic Condition Guide

•	Report ID:	27,836,988	Version:	1
	Created:	04 Dec 2025		

	Jinei	S Dasi	Condition Guide	Created:	04 Dec 2025			
Make:	Land Rover	Model:	Range Rover Sport		OK	Requires	NI/A	
Body Style:	Wagon	Year:	2014	OK Engine		Attention	N/A	
		31 Dec 2025	Oil level		<u> </u>	1		
WoF Expiry:	27 Aug 2026	Odometer:	110,270 Kms		-			
Good No.:	27836988	VIN:	SALWA2VE9EA327773	Smoke & fumes Engine performance		+	-	
Next Service:	127,097kms	Service History:	No	Noise	offiliance /	1		
lote: This report is not a warranty					-	+		
his report is a guide (only. Consideration is made dertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/h	rts have not been dismantled or from cold. The Vendor recommends a	Cooling por		+	_	
agnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a Ill mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling per	_			
Key								
	= Rust C = C			Transmissio		T	Ι	
D = Dent PT	= Paint defect $P = P$	in dent SC = Stor	ne Chips	Operation	<i>V</i>		-	
	S	P	SD	Noise	✓			
$\overline{}$				Clutch			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
				CV joints	/			
$\overline{}$				Wheel bearings				
$-\!$	8		1	Brakes				
				Performanc				
				Hand brake	•			
				Tyres (lowest observed tread depth of tyres)				
				Left front 5.5 m				
				Right front		5.5 m		
				Left rear			5 mi	
	S	P	S	Right rear		4.5 m		
lote: some defects a	and blemishes may not be	displayed in the diagra	m	Spare Yes				
Body Inspection	on Comments			Suspension	1			
				Suspension	performance 🗸			
				Steering pe	formance 🗸			
				Shock absor	bers			
Conditions Duri	ing Body Inspection		Dry	Air Conditioning / Heater				
Under Carriage	e and Under Bonnet	Inspection Comm	ents	Operation	✓			
				Electrical /	Accessories			
				Head lights	·			
				Tail lights	·			
Interior Comments				Indicators	V			
Seats:	Good			Dashboard	warning lights 🗸			
Carpets: Good			Wipers (fror	it & rear)				
Panels: Good			Window wir	nder FL 🗸				
Dashboard: Good			Window wir	nder FR 🗸				
General Comm	General Comments				nder RL 🗸			
			Window wir	nder RR 🗸				
				Rear view m	irrors			

		1		
Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Timing Cha	in	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	LukaAjitvan Woer	den		
Published by:	LukaAjitvan Woer	den		
Inspection Date:	04 Dec 2025			

have read and understood
this condition quide

NAME			

IGNATURE		

2

1

•

Radio (basic test only)

Sat. nav. (basic test only) Reversing camera

CD (basic test only)

Number of keys

Central locking Remote locking