

Basic Condition Guide

| • | Report ID: | 27,837,775 | Version: | 2 |
|---|------------|-------------|----------|---|
| | Created: | 16 Dec 2025 | | |

| Make: | Subaru | Model: | Forester | | | Requires | | |
|-----------------------|---|---|--|---|---------------------------------------|-----------|----------|--|
| Body Style: | SUV | Year: | 2017 | | OK | Attention | N/A | |
| Rego No.: | KKF166 | Rego Expiry: | 30 Jun 2026 | Engine | | | 1 | |
| WoF Expiry: | 29 Dec 2026 | Odometer: | 177,495 Kms | Oil level | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Good No.: | 27837775 | VIN: | JF2SJ9KC5HG085157 | Smoke & fumes | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Next Service: | 187,000 Kms | Service History: | Yes | Engine performance | 1 | | | |
| lote: This report is | not a warranty | , | Noise Coolant condition | 1 | | | | |
| his report is a guide | only. Consideration is mad | e for age and mileage. P been driven up to 50km/ | arts have not been dismantled or h from cold. The Vendor recommends a | | V | | | |
| ıll mechanical insp | ection prior to purchase an | d this can be arranged f | or an additional charge. | Cooling performance | 1 | | | |
| Кеу | | | ls W = Significant scuffs | Radiator / Hoses (visual) | | | | |
| | | Crack *= Deca | Transmission Operation | | | | | |
| D = Dent P | T = Paint defect P = P | in dent SC = Sto | ne Chips | Operation | 1 | | - | |
| P SC | | SD SD | S D PT W | Noise | | | 1 | |
| | | | | Clutch CV joints | 1 | | | |
| | \sim | | S PT SC W | Wheel bearings | 1 | | - | |
| S SC W | | <u> </u> | | Brakes | | <u> </u> | <u> </u> | |
| M | MATT | | | Performance | V | | I | |
| 1 | | | S SC | Hand brake | V | | | |
| s sc | to II | | | | west observed tread depth of tyres) | | | |
| 330 | | | Left front | 7.5 mm | | | | |
| | | | | Right front | | | 7.6 mm | |
| | | | Left rear | 7.6 mm | | | | |
| D | W | DP SPT | Right rear | 7.8 mn | | | | |
| latar com a dafacta | and blomishes may not be | displayed in the diagr | Spare | Yes | | | | |
| | and blemishes may not be on Comments | e dispiayed in the diagra | 3111 | Suspension | | | | |
| Stone chip in fro | | | | Suspension performance | V | | | |
| Front bumper lo | ower right side plastic | trim damaged | | Steering performance | 1 | | | |
| | | | | Shock absorbers | 1 | | | |
| Conditions Du | ring Body Inspection | | Air Conditioning / Heater | | | l | | |
| | je and Under Bonnet | Inspection Comm | Operation | V | | | | |
| 4WD | , | | Electrical / Accessories | | | | | |
| | | | | Head lights | V | | | |
| | | | | Tail lights | 1 | | | |
| Interior Comn | nents | | Indicators | 1 | | | | |
| Seats: Stains | | | | Dashboard warning lights | 1 | | | |
| Carpets: | Drivers side average | | | Wipers (front & rear) | 1 | | | |
| Panels: | | | | Window winder FL | 1 | | | |
| Dashboard: | Good | | Window winder FR | 1 | | | | |
| General Comr | | | Window winder RL | 1 | | | | |
| | es, one isn't working | | Window winder RR | 1 | | | | |
| | | | | Rear view mirrors | 1 | | | |
| | | | | near view militors | | | | |
| | | | | | V | | | |
| Road Condition | ns During Test Drive | Dry | | Radio (basic test only) CD (basic test only) | - | | | |

I have read and understood this condition guide:

Inspected by:

Published by:

Inspection Date:

Evidence of Cam Belt Replacement

Hoani Saunders

Robert Chardon

11 Dec 2025

NAME

Yes

No

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

1

Kms