

Basic Condition Guide

Report ID:	27,838,621	Version:	2
Created:	12 Dec 2025		

	ome	<u> </u>		Created:	
Make:	Mazda	Model:	Atenza		
Body Style:	Wagon	Year:	2009	Engine	
Rego No.:	PDS730	Rego Expiry:	o Expiry: 29 Dec 2025		
WoF Expiry:	23 Dec 2026	Odometer:	78,520 Kms	Oil level Smoke & fi	
Good No.:	27838621	VIN:	7AT0C139X21105694	Engine per	
Next Service:	88000kms.	Service History:	Yes	Noise	
ote: This report is	•	,		Coolant co	
agnostic testing ur	ndertaken. The vehicle has b	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling pe	
ll mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.	Radiator /	
ey = Scratch R	= Rust	: Crack *= Deca	ls W Ciamificant souffs	Transmiss	
	= Rust $C = CT = Paint defect P = P$		·	Operation	
				Noise	
S SC	W	sc s	WSP	Clutch	
				CV joints	
	$(0)_{\mathbb{F}}$		(\bigcirc)	Wheel bea	
SC W				Brakes	
M	19 11			Performar	
] —		Hand brak	
s sc	10			Tyres (low	
				Left front	
			S	Right from	
				Left rear	
S W R DW W DW					
ote: some defects	and blemishes may not be	displayed in the diagra	am .	Right rear Spare	
	on Comments	. displayed in the diagre		Suspension	
, ,			<u>, </u>	Suspensio	
				Steering p	
				Shock abs	
Conditions During Body Inspection Dry					
	je and Under Bonnet	Inspection Comm	-	Air Condi	
nderbody surf				Electrical	
-				Head light	
				Tail lights	
Interior Comn	nents			Indicators	
Seats:	Good			Dashboard	
Carpets:	Good		 	Wipers (fro	
Panels:	Good			Window w	
Dashboard:	Good			Window w	
General Comr	1			Window w	
Partial service h				Window w	
	•			Rear view	
				Radio (bas	
Road Condition	ns During Test Drive	Dry		CD (basic t	
Engine Timing		Timing Chain		Number o	
	m Belt Replacement	Yes	No Kms	Central loc	
LVIGCTICE OF Ca				CCITITATIO	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	<i>y y y y</i>		
Noise	/		
Coolant condition	V		
Cooling performance	V		
Radiator / Hoses (visual)	V		
Transmission		<u> </u>	
Operation	V		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front	•		7 mm
Right front			7 mm
Left rear			4 mm
Right rear			4 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	✓		
Indicators	·		
Dashboard warning lights	✓		
Wipers (front & rear)	/		
Window winder FL	·		
Window winder FR	/		
Window winder RL	·		
Window winder RR	/		
Rear view mirrors	·		
Radio (basic test only)	· ·		
CD (basic test only)	·		
Number of keys	2	I.	
Central locking	/		
Remote locking	<u> </u>		
Sat. nav. (basic test only)	-		
Reversing camera			·
g camera		<u> </u>	

I have read and understood this condition guide:

Inspection Date: 06 Dec 2025

Inspected by:

Published by:

NAME

Sione Mae

Neil Honeyman

SIGNATURE