

Inspected by:

Published by:

Inspection Date: 09 Dec 2025

Marlon Espena

Isaiah Talauta

Basic Condition Guide

Report ID:	27,840,656	Version:	2	
Created:	27 Dec 2025			

N/A

5.0 mm5.0 mm7.0 mm7.0 mm

1

Remote locking

Reversing camera

Sat. nav. (basic test only)

		<u> </u>		Created:	27 Dec 2025			
Make:	Mitsubishi	Model:	Outlander				Requires	
Body Style:	Wagon	Year:	2009	Engino		OK	Attention	
Rego No.:	PBN915	Rego Expiry:	18 Feb 2026	Engine Oil level				
WoF Expiry:	01 Oct 2026	Odometer:	114,012 Kms			1		
Good No.:	27840656	VIN:	7AT0CJ3MX22400553	Smoke & fumes		1		
Next Service:	114,656 kms	Service History:	No	Engine performance Noise		1		
Note: This report is	not a warranty	Coolant condition		1				
	only. Consideration is madedertaken. The vehicle has b	Cooling performance		1				
	ection prior to purchase an		Radiator / Hoses (visual)		V			
Key		Transmission						
	= Rust $C = C$ Γ = Paint defect $P = P$	Operation 🗸						
	- raint delect F - F	in dent SC = Sto	nie Chips	Noise		1		
			S	Clutch				
				CV joints		1		
	\sim		(O) s	Wheel bear	rings	1		
SD A		· · · ·)		Brakes				
M			A HIV	Performan	CO.	V		
1				Hand brake		1		
	6						turos)	
6				Tyres (lowest observed tread depth of tyres) Left front				
				Right front				
				Left rear				
	W :	SD SD	SD	Right rear				
Note and defeate		Spare Yes						
Body Inspection	and blemishes may not be on Comments	displayed in the diagra	.m	Suspension				
body inspection	on comments			•	n performance	V	Ι	
				Steering pe		1		
				Shock abso		1		
Conditions Dur	ing Body Inspection		Dry	Air Conditioning / Heater			l	
	e and Under Bonnet	Operation 🗸						
onder earnag	e and onder bonner	Electrical / Accessories						
				Head lights		V		
				Tail lights		1		
Interior Comm	nents			Indicators		1		
Seats:	Poor				l warning lights	1		
Carpets:				Wipers (front & rear)		1		
Panels:	Average			Window wi		V		
Dashboard: Average					Window winder FR			
General Comm	_		Window wi		V			
Radio screen no		Window wi	ndow winder RR					
	•			Rear view r		1		
				Radio (basi				
Road Condition	ns During Test Drive	Dry	CD (basic te					
Engine Timing		Timing Chain	Number of	· · · · · · · · · · · · · · · · · · ·	1	1		
Fyidence of Cam Belt Replacement Yes No Kms					kina	1		

I have read and understood this condition guide: NAME _______SIGNATURE