

## **Basic Condition Guide**

| • | Report ID: | 27,840,752  | Version: | 1 |
|---|------------|-------------|----------|---|
|   | Created:   | 12 Dec 2025 |          |   |

| Make:                                       | Ssangyong  | Model:   | Korando                   |  | ОК       | Requires<br>Attention | N/A  |  |
|---|--|--|---------------------------|--|----------|-----------------------|------|--|
| Body Style:                                 | SUV  | Year:  | 2011                      | Engine                                       | OK _     | Attention             | IN/A |  |
| Rego No.:                                   | FTF306   | Rego Expiry:   | 02 Jan 2026               | Oil level                                    |          |                       | 1    |  |
| WoF Expiry:                                 | 25 Nov 2026  | Odometer:  | 215,008 Kms               | Smoke & fumes                                | 1        |                       | 1    |  |
| Good No.:                                   | 27840752   | VIN:   | KPTB0A1SSBP003557         | Engine performance                           | · ·      |                       | 1    |  |
| Next Service:                               | 221000   | Service History:                                     | No                        | Noise  | · ·      |                       |      |  |
| ote: This report is                         | •  |  | Coolant condition         | V  |          |                       |      |  |
| is report is a guide<br>agnostic testing un | only. Consideration is mad<br>ndertaken. The vehicle has l | le for age and mileage. P<br>been driven up to 50km/ | Cooling performance       | V  |          |                       |      |  |
| ·   | ection prior to purchase ar                                | nd this can be arranged i                            | Radiator / Hoses (visual) | V  |          |                       |      |  |
| <b>ey</b><br>= Scratch R                    | = Rust C=0   | Crack *= Deca  | Transmission              |  |          |                       |      |  |
|   | = Rust C = C<br>T = Paint defect P = F                     |  | Operation                 | V  |          |                       |      |  |
|   |  |  |                           | Noise  | V        |                       |      |  |
|   | S  | P SC SC  | S                         | Clutch                                       |          | <u> </u>              |      |  |
|   |  |  |                           | CV joints                                    |          |                       |      |  |
|   |  |  | SSC                       | Wheel bearings                               |          |                       |      |  |
| s sc  |  |  | Brakes                    |  | <u> </u> |                       |      |  |
|   | 19r 11   |  |                           | Performance                                  | · ·      |                       |      |  |
|   |  |  | SC                        | Hand brake                                   |          |                       |      |  |
| sc  | 18 VIII  |  |                           | Tyres (lowest observed tread depth of tyres) |          |                       |      |  |
|   |  |  | Left front                |  |          | 5.2 r                 |      |  |
|   |  |  | Right front               |  | -        | 7.2 n                 |      |  |
|   |  |  | Left rear                 | 2.6 m  |          |                       |      |  |
| S   |  | s sc sc  | Right rear                |  |          | 2.5 m                 |      |  |
| ote: some defects                           | and blemishes may not be                                   | e displayed in the diagra                            | am                        | Spare  | Yes      |                       |      |  |
|   | on Comments  |  |                           | Suspension                                   |          |                       |      |  |
| Small cracks wi                             | ith legs on windscree                                      | n  |                           | Suspension performance                       | V        |                       |      |  |
| linor stonechip                             | os on windscreen   |  |                           | Steering performance                         | V        |                       |      |  |
|   |  |  |                           | Shock absorbers                              | V        |                       |      |  |
| Conditions Dur                              | ring Body Inspection                                       |  | Air Conditioning / Heater |  | ,        |                       |      |  |
| Under Carriag                               | je and Under Bonne   | t Inspection Comn                                    | nents                     | Operation                                    |          | ~                     |      |  |
| ront wheel driv                             | /e   |  | Electrical / Accessories  |  | •        |                       |      |  |
|   |  |  |                           | Head lights                                  |          | ~                     |      |  |
|   |  |  |                           | Tail lights                                  | ·        |                       |      |  |
| Interior Comments                           |  |  |                           | Indicators                                   | ·        |                       |      |  |
| Seats:                                      | Good   |  |                           | Dashboard warning lights                     | /        |                       |      |  |
| Carpets:                                    | Good   |  |                           | Wipers (front & rear)                        | V        |                       |      |  |
| Panels:                                     | Good   |  |                           | Window winder FL                             | V        |                       |      |  |
| Dashboard:                                  | Good   |  | Window winder FR          | V  |          |                       |      |  |
| General Comr                                | ments  |  | Window winder RL          | -  |          |                       |      |  |
|   | light not working  |  |                           | Window winder RR                             | -        |                       |      |  |
| /C not cold                                 |  |  |                           | Rear view mirrors                            |          |                       |      |  |
|   |  |  |                           | Radio (basic test only)                      |          |                       |      |  |
| Road Condition                              | ns During Test Drive                                       | Dry  |                           | CD (basic test only)                         |          | <u> </u>              | -    |  |
| Engine Timing                               |  | Timing Chain   | Number of keys            | 1  |          |                       |      |  |
|   |  |  |                           | ,  |          |                       |      |  |

I have read and understood this condition guide:

Inspection Date: 12 Dec 2025

Inspected by:

Published by:

Evidence of Cam Belt Replacement

NAME

Cameron Senior-Arnold

Holden Milne-Smith

No

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms