

Basic Condition Guida

•	Report ID:	27,841,674	Version:	1
	Created:	05 Dec 2025		

	umer	S Dasi	C Condition Guide	Created:	05 Dec 2025			
Make:	Ford	Model:	Ecosport				Requires	
Body Style:	SUV	Year:	2016			OK	Attention	N/A
Rego No.:	RNH452	Rego Expiry:	26 Jan 2026	Engine				1
WoF Expiry:	27 Mar 2026	Odometer:	138,500 Kms					
Good No.:	27841674	VIN:	MAJBXXMRKBGR64361	Smoke & fu				
Next Service:	0	Service History:	Yes	Engine per	formance			
Note: This report is	ļ		110.00			-		
This report is a guide	only. Consideration is mad	le for age and mileage. Pa	arts have not been dismantled or h from cold. The Vendor recommends a				-	
full mechanical inspe	ection prior to purchase an	nd this can be arranged f	or an additional charge.	Cooling pe				
Key					Hoses (visual)	/		
S = Scratch R = Rust C = Crack *= Decals W = Significant scuffs				Transmiss	on		I	ı
D = Dent P1	Γ = Paint defect $P = P$	Pin dent SC = Sto	ne Chips	Operation		·		
		Р	PT	Noise Clutch		✓		
								'
	(O)=			CV joints		·		
PT (1		Wheel bea	rings			<u> </u>
M	18			Brakes			I	ı
1			PT	Performan				
				Hand brake		/	L ,	
(A)				Tyres (lowest observed tread depth of tyres)				
				Left front				4 mm
				Right front Left rear				4 mm
PT	PT							4 mm
								4 mm
	and blemishes may not be	e displayed in the diagra	am 	Spare Yes				
Body Inspection	on Comments			Suspensio			Ī	ı
				-	performance	<u>/</u>		
					erformance	<i>\</i>		
C 1::: D				Shock abso				
	ring Body Inspection		Dry	Air Conditioning / Heater				
Under Carriag	e and Under Bonnet	t Inspection Comm	nents	Operation				
					Accessories		Ī	I
				Head lights	5	<i>'</i>		
1				Tail lights		<u> </u>		
Interior Comm				Indicators	t P. late	· ·		
Seats:	Good			Dashboard warning lights		-		
Carpets:	Good			Wipers (fro		<u> </u>		
Panels: Good				Window w				
Dashboard: Good General Comments					inder FR	<i>\</i>		
		Window w		<u>/</u>				
not working.	battery warnings on	Window w		<u> </u>	-			
-				Rear view r		~	-	
Dond Complies	no Duning T- et Duis	Dn/			c test only)		-	
	ns During Test Drive	Dry		CD (basic to	-	1		<u> </u>
Engine Liming	gine Timing Mechanism Cambelt		Number of	keys	1			

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 05 Dec 2025

Eleoit Kumar

Eleoit Kumar

NAME			

✓ No

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Yes

SIGNATURE			

1

•