

# **Basic Condition Guide**

•	Report ID:	27,841,724	Version:	4
	Created:	12 Dec 2025		

	ОК	Requires Attention	N/A
Engine	- OK	Attention	IN/A
Oil level	·		
Smoke & fumes	_		
Engine performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission	_		
Operation	·	1	
Noise	1		
Clutch	•		_
CV joints	1		
Wheel bearings	1		
Brakes		l	
Performance	V		
Hand brake	1		<u> </u>
Tyres (lowest observed tread o	lenth of	tvres)	
Left front			5.0 mm
Right front			5.0 mm
Left rear			7.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension	100		
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation Operation	1	I	l
Electrical / Accessories			<u> </u>
	<b>/</b>	I	l
Head lights	V		
Tail lights Indicators	V		
	~		
Dashboard warning lights	1		
Wipers (front & rear) Window winder FL	~	-	
Window winder FL Window winder FR	V		
		-	
Window winder RL Window winder RR	<b>/</b>	-	
Rear view mirrors	1	-	
	1		
Radio (basic test only)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		<u>, , , , , , , , , , , , , , , , , , , </u>
CD (basic test only)	1	<u> </u>	
Number of keys	1	Ι	1
Central locking	1		
Remote locking	<b>-</b>		.,
Sat. nav. (basic test only)	1	1	, v


Make:	Suzuki	Model:	Swift
Body Style:	Hatchback	Year:	2022
Rego No.:	PBE728	Rego Expiry:	15 Feb 2026
WoF Expiry:	19 Mar 2026	Odometer:	54,525 Kms
Good No.:	27841724	VIN:	JSAAZC83S00406061
Next Service:	59,000km	Service History:	Yes

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

#### Kev

itey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Grab handles in car, need refit. RR seat belt refit. Parcel tray missing.R bumper Left reflector missing. Grille centre black trim cracked. R bumper refit. F bumper crack. LF tyre sidewall damage. RF seat belt beginning to fray.

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Interior Comm	ents
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good
General Comments	

### FWD. Windscreen crack in cva.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Cha	ain	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by: Sharnae Smith				
Published by:	Sharnae Smith			

I hav	ve read	and	understood
thic	conditi	on a	uide.

Inspection Date: 12 Dec 2025

NAME		

110	SN	ΔΤΙ	IR	F	

Reversing camera