

•	Report ID:	27,842,052	Version:	1
	Created:	08 Dec 2025		

N/A

4.5 mm 5.0 mm 5.0 mm 6.0 mm

A T.		Doo!	o Condition Cuido	Report ID: 27	7,842,052	Ve	rsion:	1
	nue	S Basi	c Condition Guide	Created: 08	3 Dec 2025			
Make:	Volkswagen	Model:	Golf				Requ	ires
Body Style:	Hatchback	Year:	2008			OK	Atten	tion
Rego No.:	LHS7	Rego Expiry:	21 Dec 2025	Engine				
WoF Expiry:	14 Jan 2026	Odometer:	111,373 Kms	Oil level		/		
Good No.:	27842052	VIN:	WVWZZZ1KZ8U012781	Smoke & fumes		/		
Next Service:	120000	Service History:	No	Engine performance		✓		
		Service History.		Noise				
lote: This report is his report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant condit	✓			
	ndertaken. The vehicle has b ection prior to purchase an		n from cold. The Vendor recommends a or an additional charge.	Cooling perfor	/			
Key				Radiator / Hoses (visual)		/		
-	= Rust $C=C$	rack *= Deca	s W = Significant scuffs	Transmission				
D = Dent P	T = Paint defect P = Paint defect	in dent SC = Stor	ne Chips	Operation		/		
		SC	SD	Noise		/		
-				Clutch				
			SPT	CV joints		/		
			Wheel bearings		/			
SC A			Brakes					
			Performance		/			
			Hand brake		/			
SC	18	Tyres (lowest observed tread depth of tyres)						
		Left front		4				
		Right front		5				
			Left rear			5		
s)[Right rear				6		
Note: some defects	and blemishes may not be	Spare	Yes					
Body Inspecti	on Comments			Suspension				
Minor chip on w	vindscreen			Suspension pe	erformance	/		
				Steering perfo	rmance	/		
				Shock absorbe	ers	/		
Conditions Du	ring Body Inspection		Dry	Air Condition	ing / Heater			
	je and Under Bonnet	Operation						
Front wheel driv	<u> </u>	·		Electrical / Ac	cessories			
Transmission leak			Head lights		/			
				Tail lights		/		
Interior Comments			Indicators					
Seats: Good				Dashboard wa	rning lights	/		
Carpets: Good				Wipers (front 8		· ·		
Panels:	Average			Window winde		~		
i di icis.	, .voiago			TVIII GOVV VVIII GO	C L			

Carpets:	Good					
Panels:	Average					
Dashboard:	Good					
General Comm	eneral Comments					
Bonnet struts needs refilling or replacement Slight tick Compartment under steering wheel does not close Service date is coming up soon (would recommend a service)						
Road Condition	s During Test Drive	Dry				
Engine Timing N	Mechanism	Timing Chain				
Evidence of Cam Belt Replacement		Yes	No	Kms		
Inspected by:	Jaykib Collins					
Published by:	Janine Bell					
Inspection Date:	07 Dec 2025					

SIGNATURE		

1

1

1 1

2

1

1

Window winder FR Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

I	ha	ve	rea	d	an	d	un	de	ers	to	OC	Į
t	his	co	nd	itio	on	g	uic	de:				