

•	Report ID:	27,842,109	Version:	4
	Created:	17 Dec 2025		

N/A

4.0 mm 5.0 mm 2.0 mm 4.0 mm

U	ntuer	S Basi	c Condition Guide	Created:	17 Dec 2025		
Make:	Mitsubishi	Model:	Pajero				Requires
Body Style: Wagon		Year:	2008			OK	Attention
Rego No.: MUG522		Rego Expiry:	06 Mar 2026	Engine			
WoF Expiry:	07 Mar 2026	Odometer:	186,701 Kms	_ Oil level		/	<u> </u>
Good No.:	27842109	VIN:	7AT0CJ08X19100291	Smoke & fumes		_	
Next Service:	unknown	Service History:	No	Engine performance		/	
Note: This report is not a warranty			110	Noise		/	
This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant condition		/	<u> </u>
			ven up to 50km/h from cold. The Vendor recommends a an be arranged for an additional charge.		Cooling performance		
Key				Radiator / H	Hoses (visual)	/	
	= Rust $C = C$	rack *= Deca	ls W = Significant scuffs	Transmiss	ion		
D = Dent P1	$\Gamma = Paint defect P = Pi$			Operation		/	
		S P SC	SC	Noise		/	
S P SC SC				Clutch			
			CV joints		/		
				Wheel bearings 🗸			
				Brakes			
			Performan	ce	V		
			Hand brake				
SC				Tyres (lowest observed tread depth of tyres)			
				Left front			-
			S	Right front			
				Left rear			
SC	S	P SC		Right rear			
Note: some defects	and blemishes may not be	displayed in the diagra	m	Spare		Yes	
Body Inspection		. , , , , ,		Suspensio	n		
Left wing mirror casing broken.				Suspension	n performance	1	
				Steering pe	erformance	1	
				Shock abso	orbers	1	1
Conditions During Body Inspection Dry Under Carriage and Under Bonnet Inspection Comments				Air Conditioning / Heater			
				Operation			
				Electrical /	Accessories		
				Head lights		V	
				Tail lights		1	
Interior Comm	nents			Indicators		1	1
Seats: Average 3rd row headrests missing.		Dashboard	warning lights	1	1		

Interior Comments		
Seats: Average 3rd row headrests missing.		
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

7 seater 4WD SUV .

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by: Daryll Timms				
Published by: Gemma Rowland		s		
Inspection Date:	08 Dec 2025			

SIGNATURE			

1

1

1

1 1

1

1

1

Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

I have read and understood
this condition guide: