

Basic Condition Guide

•	Report ID:	27,842,243	Version:	1
	Created:	08 Dec 2025		

N/A

6.0 mm 6.0 mm 5.0 mm 5.0 mm

		Posi	a Canditian Cuida	7- 7-				
	ntuet	<u>Dasi</u>	c Condition Guide	Created: 08 Dec 2025	1			
Make:	Mitsubishi	Model:	Triton		OK	Requires Attention		
Body Style:	Utility	Year:	2012	Engine		Attention		
Rego No.:	LLJ108	Rego Expiry:	18 Dec 2025	Oil level	V		Т	
WoF Expiry:	28 Nov 2026	Odometer:	186,485 Kms	Smoke & fumes	· ·		\dagger	
Good No.:	27842243	VIN:	MMAJYKB40BD014746	Engine performance	· ·		\dagger	
Next Service:	188000	Service History:	No	Noise	· ·		\dagger	
Note: This report is		,		Coolant condition	V		†	
diagnostic testing u	ndertaken. The vehicle has b	een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a	Cooling performance	V		†	
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.	Radiator / Hoses (visual)	V		†	
Key	Don't C. C.	·	l- \\\ C:::::	Transmission			_	
	= Rust $C = CT = Paint defect P = P$		3	Operation	· ·		Т	
				Noise	/		\dagger	
sc		W PT W	SDR	Clutch			\dagger	
				CV joints			†	
				Wheel bearings			†	
SPTW				Brakes				
	19/1		PT	Performance	· ·		T	
		Hand brake			†			
PT	18 V			Tyres (lowest observed tread depth of tyres)				
				Left front			6.	
			DW	Right front			6.	
				Left rear			5.	
SCW			SDW	Right rear			5.	
Note: some defects	and blemishes may not be	e displayed in the diagra	ım	Spare Yes			_	
	ion Comments			Suspension				
Left fog light cr	acked			Suspension performance			T	
Brake lite not w	vorking			Steering performance	1		Ť	
				Shock absorbers	1		Ť	
Conditions During Body Inspection Dry				Air Conditioning / Heater	r		İ	
Under Carria	ge and Under Bonnet	Operation	V		T			
Rust in floor pa	n close to left body mo	ount behind front w	heell	Electrical / Accessories		•	Ť	
				Head lights	V		T	
				Tail lights		V	†	
Interior Comments			Indicators	V		1		
Seats:	eats: Good		Dashboard warning lights	V		1		
Carpets:	Good			Wipers (front & rear)			Ť	
Panels:	Good			Window winder FL	V		Ť	
			·			 	+	

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	119,075 Kms
Inspected by:	Greg Morgan			
Published by:	Sean Butcher			
Inspection Date:	08 Dec 2025			

I have read and und	derstood
this condition auid	e:

NAME		

SIGNATURE			

1 1

1

1

1

1

Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera