

| • | Report ID: | 27,842,788 | Version: | 3 | |
|---|------------|-------------|----------|---|--|
| | Created: | 11 Dec 2025 | | | |

Requires Attention

N/A

4.0 mm 5.0 mm 8.0 mm 5.0 mm

| U | nuer | S Basi | C Condition Guide | Created: | 11 Dec 2025 | | | |
|---------------------------|--|--|--|--|----------------|-----|------|--|
| Make: KIA | | Model: | Sorento | | | | Req | |
| Body Style: SUV | | Year: | 2015 | Functions | | OK | Atte | |
| Rego No.: HWT903 | | Rego Expiry: | 27 Jul 2026 | Engine | V | | | |
| WoF Expiry: 02 Dec 2026 | | Odometer: | 155,388 Kms | Oil level | | 1 | | |
| Good No.: | 27842788 | VIN: | KNAKU814SE5564622 | Smoke & fumes | | 1 | | |
| Next Service: 165000 kms | | Service History: | No | Engine performance | | 1 | | |
| Note: This report is r | not a warranty | | | Noise Coolant co | 1 | _ | | |
| This report is a guide of | only. Consideration is made dertaken. The vehicle has b | e for age and mileage. Pa een driven up to 50km/h | arts have not been dismantled or n from cold. The Vendor recommends a | Cooling pe | 1 | | | |
| | ction prior to purchase and | | | | 1 | | | |
| Key | | | | | Hoses (visual) | | | |
| | = Rust C = C | | | | | | | |
| D = Dent PT | = Paint defect $P = Pi$ | in dent SC = Stor | ne Chips | Operation | 1 | | | |
| | S S | 3 D P | | Noise Clutch | | | | |
| | | | | | 1 | | | |
| | \sim | | (O) s | CV joints | 1 | | | |
| S SC | | <u> </u> | | Wheel bearings Brakes | | | | |
| MI | De la | | AH | Performance | | V | l | |
| 11 | | Hand brake | | 1 | | | | |
| SC | 0 1 | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | - | | Left front | | | | |
| | | Right front | | | | | | |
| | | Left rear | · | | | | | |
| SD | S | | Right rear | | | | | |
| Natarasas dafaata | | diambarra dia tha dia arra | | Spare Yes | | | | |
| Body Inspectio | and blemishes may not be | displayed in the diagra | ım | Suspension | | | | |
| body mapeetic | on comments | | | - | n performance | V | Π | |
| | | | | - | erformance | 1 | | |
| | | | | Shock abso | | 1 | | |
| Conditions Duri | ing Body Inspection | Air Conditioning / Heater | | | | | | |
| | e and Under Bonnet | Operation • | | | Ι | | | |
| Onder Carriage | and officer pointer | mspection comm | | | / Accessories | | | |
| | | | | Head light: | | V | Π | |
| | | | | Tail lights | | 1 | | |
| Interior Comments | | | | | | · / | | |
| Seats: | Average | Indicators Dashboard | I warning lights | · / | | | | |
| Carpets: Good | | | | | nt & rear) | 1 | | |
| Panels: Average | | | | | inder FL | 1 | | |
| | | | | | | | | |

| Poad Condition | s During Test Drive | Dry |
|----------------------------------|---------------------|--------------|
| Noau Cortuition | s During lest Drive | ыу |
| Engine Timing I | Mechanism | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Eleoit Kumar | |
| Published by: | Sam Huang | |
| Inspection Date: | 08 Dec 2025 | |

| SIGNATURE | | | |
|-----------|--|--|--|

1

1

1 1

2

1 1

Window winder FR

Window winder RL Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

| I | ha | ve | rea | d | an | d | un | de | ers | to | OC | Į |
|---|-----|----|-----|------|----|---|-----|-----|-----|----|----|---|
| t | his | СО | nd | itio | on | g | uic | de: | | | | |

Good

Dashboard:

General Comments