


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Volkswagen | Model: | T5 |
| Body Style: | Van | Year: | 2014 |
| Rego No.: | JTS231 | Rego Expiry: | 30 Jul 2026 |
| WoF Expiry: | 19 Dec 2025 | Odometer: | 252,076 Kms |
| Good No.: | 27842790 | VIN: | WV1ZZZ7HZEH117678 |
| Next Service: | 266000 | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Tailgate large dent

Conditions During Body Inspection
Under Carriage and Under Bonnet Inspection Comments

Some oil seepage

Interior Comments

Seats: Average

Carpets: Average

Panels: Average

Dashboard: Average

General Comments

One key broken

ABS / Traction control fault, warning lights displayed

| | | | |
|-----------------------------------|------------------------------|--|-----|
| Road Conditions During Test Drive | Dry | | |
| Engine Timing Mechanism | Cambelt | | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No | Kms |
| Inspected by: | Kilipati Mae | | |
| Published by: | Kilipati Mae | | |
| Inspection Date: | 10 Dec 2025 | | |

I have read and understood
this condition guide:

NAME _____

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,842,790 | Version: | 1 |
| Created: | 10 Dec 2025 | | |

| | OK | Requires Attention | N/A |
|---|-----|--------------------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | | ✓ | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | 4 mm | |
| Right front | | 4 mm | |
| Left rear | | 8 mm | |
| Right rear | | 8 mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | | ✓ | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | | | ✓ |
| Window winder RR | | | ✓ |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 3 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

SIGNATURE _____