•	Report ID:	27,842,960	Version:	1
	Created:	16 Dec 2025		

	ОК	Requires Attention	N/A
Engine	OK.	7.00011	. 4/1
Oil level	V		
Smoke & fumes	· /		
00627087 Engine performance	V		
Noise	· /		
Coolant condition	V		
mantled or or recommends a Cooling performance	V		
Radiator / Hoses (visual)	V		
ignificant scuffs Transmission			
Operation	V		
Noise			
S	/		
CV joints			
S W Wheel bearings	· /		
Brakes		l	<u> </u>
Performance			Ι
Hand brake	-		
Tyres (lowest observed t		tvras)	l
Left front	licad acpairor		5.0 mn
S SC Right front			5.0 mr
Left rear			1.5 mr
n e			1.5 mr
Right rear	Yes		1.5 mi
Spare	165		
Suspension		Γ	I
Suspension performance			
Steering performance	<i>V</i>		
Shock absorbers	V		
Air Conditioning / Hear		I	Г
Operation			
Electrical / Accessories		I	
Head lights	•		
Tail lights	/		
Indicators	<i>'</i>		
Dashboard warning ligh			
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	<i>'</i>		
Window winder RR	V		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	2		
Kms Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			/
Reversing camera	V		

SIGNATURE

O T	nuer	S Basi	c Condition Guide
Make:	Suzuki	Model:	Vitara
Body Style:	SUV	Year:	2019
Rego No.:	MQB251	Rego Expiry:	30 Jun 2026
WoF Expiry:	08 Aug 2026	Odometer:	114,172 Kms
Good No.:	27842960	VIN:	TSMLYD21S00627087
Next Service:	127857	Service History:	No
diagnostic testing und		een driven up to 50km/h	orts have not been dismantled or from cold. The Vendor recommends a or an additional charge.
•	= Rust C = C	rack * = Decal	ls W = Significant scuffs
D = Dent PT	= Paint defect $P = Pi$	n dent SC = Stor	•
S S S S S S S S S S S S S S S S S S S		SC S W	S W S S S S
Note: some defects a	and blemishes may not be	displayed in the diagra	m
Body Inspection			
Chips on windso Door handles pa			
Conditions Duri	ng Body Inspection		Dry

Under Carriage and Under Bonnet Inspection Comments

back seats stained

Dry

Timing Chain

No

Yes

Average Average

Average

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 11 Dec 2025

I have read and understood this condition guide:

Beatrice Nelson

James Scott

Engine Timing Mechanism

Inspected by:

Published by:

Interior Comments

General Comments

Seats:

Carpets:

Panels:

Dashboard: