

Basic Condition Guide

•	Report ID:	27,843,093	Version:	1
	Created:	12 Dec 2025		

	Ulliel	<u> </u>		Created: 12	2 Dec 2025			
Make:	Honda Model: Torneo			Requires				
Body Style:	Sedan	Year:	2001		OK	Attention	N/A	
Rego No.:	FPE6	Rego Expiry:	24 Jul 2026	Engine			1	
WoF Expiry:	23 Jan 2026			Oil level				
Good No.:			7AT08G8TX10212399	Smoke & fumes		<u> </u>	-	
		Service History:		Engine perfor				
Note: This report is		Je. 1.ee 1J.01)	Noise	<i>,</i>				
This report is a guide	e only. Consideration is mad	de for age and mileage.	Coolant condi			ļ		
full mechanical insp	ndertaken. The vehicle has bection prior to purchase ar	nd this can be arranged	Cooling perfo	rmance	ļ	<u> </u>		
Key			Radiator / Hos	es (visual)				
S = Scratch R	C = Rust $C = C$	Crack *= Dec	cals W = Significant scuffs	Transmission				
D = Dent P	T = Paint defect P = F	Pin dent $SC = St$	Operation	/				
SC	SI	D PT P S D PT	P S SP	Noise	<i>'</i>			
		T		Clutch			~	
	\ \(\)		SDPTW	CV joints	V			
S PT SC W	MA UT	1		Wheel bearing	gs 🗸			
S PT SC W				Brakes				
			PT SC	Performance	✓			
		$\parallel \parallel \parallel \parallel$	FISC	Hand brake	✓			
S SC	18			Tyres (lowest observed tread depth of tyres)				
				Left front	Left front 6.0 mm			
			SDPTP	Right front		6.0 mm		
				Left rear		6.2 mm		
S SC	<u>s</u> <u>s</u>	D PT P S D PT	P S SRP	Right rear		6.4 mm		
Note: some defects	and blemishes may not be	e displayed in the diad	ıram	Spare	Yes	Yes		
Body Inspecti	ion Comments			Suspension				
Surface rust ar	ound inside of boot lic	d frame & at botton	m of rear window. Badge missing	Suspension pe	erformance 🗸			
off boot lid.				Steering perfo	ormance 🗸			
				Shock absorbe	ers 🗸			
Conditions Du	ring Body Inspection		Dry	Air Condition	ing / Heater		•	
	ge and Under Bonne	t Inspection Com		Operation	· /			
		-		Electrical / Ac	cessories			
				Head lights	V			
				Tail lights	V			
Interior Comr	ments			Indicators	V			
Seats:	Good			Dashboard wa	arning lights 🗸			
Carpets:	Average			Wipers (front 8				
Panels:	Good		Window wind					
Dashboard:	Good		Window wind					
General Com			Window wind					
Radio is not wo				Window wind		 		
radio io not we	mang.			Rear view mirr				
							 	
Dood Condition	no Duning To at Dui	Dn/		Radio (basic te	-	<i>'</i>	-	
	ns During Test Drive	Dry Timing Chain	CD (basic test	-				
Engine Timing			Number of key	, ,	Τ	Г		
Evidence of Cam Belt Replacement Yes No Kms			Central locking	_	 			
Inspected by:	Jason Young			Remote locking	ng 🗸		1	

I have read and understood this condition guide:

Published by:

Inspection Date:

NAME

Glen Charlton

10 Dec 2025

SIGNATURE

Sat. nav. (basic test only)

Reversing camera