

Basic Condition Guide

•	Report ID:	27,844,244	Version:	1
	Created:	09 Dec 2025		

	Ullie			Created:	09 Dec 2025				
Make:	Hyundai Model: Tucson			Requires					
Body Style:	SUV	Year:	2009			OK	Attention	N/A	
Rego No.:	FAC275	Rego Expiry:	25 Feb 2026	Engine			<u> </u>	1	
WoF Expiry:	30 Sep 2026			Oil level		/			
Good No.:			KMHJN81BR9U069628	Smoke & f		/			
Next Service: 256226		Service History:			erformance	/			
		Service History.	Noise		/				
Note: This report is This report is a guide	e only. Consideration is mad	de for age and mileage.	Coolant co	ondition	/				
diagnostic testing u full mechanical insp	ndertaken. The vehicle has bection prior to purchase a	been driven up to 50kn nd this can be arrange	Cooling p	erformance	/				
Key		,	Radiator /	Hoses (visual)					
•	R = Rust $C = 0$	Crack *= De	cals W = Significant scuffs	Transmis	sion				
D = Dent P	PT = Paint defect P = P	Pin dent $SC = St$	Operation	1	/				
SSC	S	D SC S SC	S	Noise		1			
				Clutch				~	
			SSC	CV joints		/			
	TA UT	+		Wheel be	arings	/			
S SC				Brakes					
				Performa	nce	1			
			sc	Hand bral	ke	~			
SC	18			Tyres (lowest observed tread depth of tyres)					
		1		Left front				4.4 mn	
			S	Right fron	it	4.4 mm			
				Left rear		5.5 mm			
s		s sc s sc	S	Right rear		5.2 mm			
Note: some defects	s and blemishes may not b	e displayed in the diad	aram	Spare		Yes			
	ion Comments			Suspensi	on	ı			
Minor stonechi	ps on windscreen			Suspensio	on performance	~			
				Steering p	performance	1			
				Shock abs		1			
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater					
	ge and Under Bonne	t Inspection Com	Operation		/				
4WD	2 .			Electrical	Electrical / Accessories				
				Head ligh	ts		·		
				Tail lights		1			
Interior Comr	ments			Indicators		_			
Seats:	Good				d warning lights	1			
Carpets:	Good				ont & rear)	1			
Panels:	Good		Window		1				
Dashboard:	Good	Window		1					
General Com			Window		1				
	/ also brown bits in ra	diator	Window		1				
	light not working			Rear view		1			
					sic test only)	1		 	
Road Conditio	uns During Tost Drive	Dry	CD (basic	•			1		
Road Conditions During Test Drive Dry Engine Timing Mechanism Cambelt				Number o		2	<u> </u>		
			Central lo		<i>'</i>	1			
Evidence of Cam Belt Replacement Yes No Kms Inspected by: Cameron Senior-Arnold					1	-	 		
Inspected by:	anieron senior	-AITIUIU		Remote lo	icking	"	1	1	

I have read and understood this condition guide:

Inspection Date: 09 Dec 2025

Janine Bell

Published by:

NAME ____

SIGNATURE

Sat. nav. (basic test only)

Reversing camera