

Basic Condition Guide

Report ID:	27,844,285	Version:	1
Created:	10 Dec 2025		

Make:	Suzuki	Model:	Ignis		
Body Style:	Hatchback	Year:	2016		
Rego No.:	RDD202	Rego Expiry:	29 Sep 2025		
NoF Expiry:	02 Dec 2025	Odometer:	114,244 Kms		
Good No.:	27844285	VIN:	7AT0GKDTX24115419		
Next Service:	120176 kms	Service History:	No		
agnostic testing un	only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends or an additional charge.		
	= Rust $C = C$ = Paint defect $P = Pi$		lls W = Significant scu ne Chips		
SD			SD		
SD	8				
ote: some defects a	and blemishes may not be	displayed in the diagra	am		
Body Inspection carcel tray missemount play,		orking and both fog	light, both front shock strut		
Conditions Dur	ing Body Inspection		Dry		
	e and Under Bonnet	Inspection Comm			
g					
Interior Comm	ents				
eats:	Good				
Carpets:					
Panels:	Good Good				
Dashboard: Good					
General Comn					
Road Condition	s Durina Test Drive	Dry			
Road Condition	s During Test Drive Mechanism	Dry Timing Chain			

		Requires	
	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	✓		
Engine performance	✓		
Noise	\(\tau\)		
Coolant condition			
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	✓		
Noise	✓		
Clutch			V
CV joints	✓		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front			6 mm
Right front			6 mm
Left rear			6 mm
Right rear			6 mm
Spare	N/A		
Suspension			
Suspension performance		>	
Steering performance	/		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	✓ ✓		
Window winder FL	V		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	~		
CD (basic test only)			/
Number of keys	1		
Central locking	✓		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	✓		

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 10 Dec 2025

Marlon Espena

Marlon Espena

NAME

No

SIGNATURE