

Basic Condition Guide

| Report ID: | 27,844,445 | Version: | 1 | |
|------------|-------------|----------|---|--|
| Created: | 08 Dec 2025 | | | |

| | Jillei | 5 | | Created: | 08 Dec 2025 | | | | | |
|---|---|-----------------------------|---------------------------|-------------|--|----------|-----------|------|--|--|
| Make: | Toyota | Model: | Hilux | | | O!′ | Requires | N1/2 | | |
| Body Style: | Utility | Year: | 2019 | Engino | | OK | Attention | N/A | | |
| Rego No.: | LYT185 | Rego Expiry: | 29 Jan 2026 | | Engine | | | | | |
| WoF Expiry: | 04 Nov 2026 | Odometer: | 87,451 Kms | | Oil level | | | | | |
| Good No.: | 27844445 | VIN: | MR0HA3CD800717022 | | | 1 | | | | |
| Next Service: | 103000 | 103000 Service History: Yes | | rformance | <i>y</i> | | | | | |
| Note: This report is | not a warranty | , | Noise | | | | | | | |
| This report is a guide | only. Consideration is mad dertaken. The vehicle has k | le for age and mileage. P | | | 1 | | | | | |
| | ection prior to purchase ar | | erformance | / | | | | | | |
| Key | | | | | Radiator / Hoses (visual) | | | | | |
| | | Crack * = Deca | 3 | | Transmission | | | | | |
| D = Dent PT | = Paint defect $P = P$ | Pin dent SC = Sto | ne Chips | Operation | | <i>,</i> | | | | |
| | | | | Noise | | <i>'</i> | | | | |
| | | | | Clutch | | / | | | | |
| | \sim | | (0) | CV joints | | / | | | | |
| | | | Wheel bearings 🗸 | | | | | | | |
| $\neg \neg \neg$ | 8 | | | | Brakes | | | | | |
| 1 | | | | Performar | | / | | | | |
| | | | | Hand brak | | ' | | | | |
| () () | | | | - | Tyres (lowest observed tread depth of tyres) | | | | | |
| | | | | Left front | | | | 5 mm | | |
| | | | | Right fron | t | | | 5 mm | | |
| | \leftarrow | P | | Left rear | ar 4 | | | 4 mm | | |
| | | P | | Right rear | light rear 4 mm | | | 4 mm | | |
| Note: some defects a | and blemishes may not be | e displayed in the diagra | am | Spare | Spare Yes | | | | | |
| Body Inspection | on Comments | | | Suspension | on | 1 | 1 | | | |
| | | | | Suspensio | n performance | • | | | | |
| | | | | Steering p | erformance | / | | | | |
| | | | | Shock abs | orbers | • | | | | |
| Conditions Dur | ing Body Inspection | Air Condi | Air Conditioning / Heater | | | | | | | |
| Under Carriag | e and Under Bonne | t Inspection Comn | Operation | | ' | | | | | |
| | | | | Electrical | / Accessories | | | | | |
| | | | | Head light | S | • | | | | |
| | | | | Tail lights | | • | | | | |
| Interior Comm | ents | | | Indicators | | • | | | | |
| Seats: | Good | | | Dashboard | d warning lights | 1 | | | | |
| Carpets: | Good | | | Wipers (fro | ont & rear) | 1 | | | | |
| Panels: Good | | | | | vinder FL | • | | | | |
| Dashboard: | Good | Window w | vinder FR | / | | | | | | |
| General Comn | nents | | Window w | vinder RL | / | | | | | |
| | | | | Window w | vinder RR | / | | | | |
| | | | | Rear view | mirrors | 1 | | | | |
| | | | | Radio (bas | ic test only) | 1 | | | | |
| Road Condition | ns During Test Drive | Dry | CD (basic t | est only) | | | 1 | | | |
| Engine Timing Mechanism Timing Chain | | | | | f keys | 2 | | | | |
| Evidence of Cam Belt Replacement Yes No Kms | | | | | king | 1 | | | | |
| Inspected by: Kilipati Mae | | | | | cking | 1 | | | | |

I have read and understood this condition guide:

Inspection Date: 08 Dec 2025

Kilipati Mae

Published by:

NAME _____

SIGNATURE

Sat. nav. (basic test only)

Reversing camera