

## **Basic Condition Guide**

•	Report ID:	27,846,508	Version:	1	
	Created:	17 Dec 2025			

	urner	<u>Dasi</u>	C Condition Guide	Created:	17 Dec 2025				
Make:	Toyota	Model:	Hilux			OK	Requires		
Body Style:	Utility	Year:	2020	Engine		OK	Attention	N/A	
Rego No.:	QNJ37	Rego Expiry:	23 Oct 2025	Oil level		<b>/</b>	<u> </u>		
WoF Expiry:	17 Jun 2026	Odometer:	189,213 Kms	Smoke & fumes		<b>1</b>			
Good No.:	27846508	VIN:	MR0GA3DD600264710	Engine performance		<b>'</b>			
Next Service:	198,000 kms	Service History:	Yes	Noise		<b>1</b>			
Note: This report is	not a warranty		Coolant condition						
This report is a guide diagnostic testing ur	e only. Consideration is made adertaken. The vehicle has b	Cooling pe		<b>V</b>		-			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.						~			
Кеу		Radiator / Hoses (visual)  Transmission							
	= Rust C = C								
D = Dent P	T = Paint defect P = P	Operation		<i>'</i>					
S (		Noise		•					
		Clutch							
	(O)E		S	CV joints		<b>V</b>		<u> </u>	
S					Wheel bearings				
-	18			Brakes			ı		
1				Performan		<b>/</b>			
				Hand brake		~			
				Tyres (lowe	Tyres (lowest observed tread depth of tyres)				
		+		Left front				6 mr	
				Right front				7 mr	
		P D		Left rear			8 mn		
	W	Right rear 8			8 mn				
Note: some defects	and blemishes may not be	displayed in the diagra	ım	Spare	Spare Yes				
Body Inspecti	on Comments			Suspensio	Suspension				
Windscreen sto	one chip cracked			Suspension	n performance	1			
				Steering pe	erformance	•			
				Shock abso	orbers	/			
Conditions Du	ring Body Inspection		Air Conditioning / Heater						
Under Carriag	je and Under Bonnet	Operation		/					
Rwd				Electrical / Accessories					
				Head light:	5	~			
				Tail lights		~			
Interior Comn	nents			Indicators		1			
Seats:	FR seat base pad	l torn		Dashboard	l warning lights	•			
Carpets:	Good			Wipers (fro	Wipers (front & rear)				
Panels:	Good			Window w		1			
Dashboard: Good					inder FR	1			
General Comr	ments			Window w	inder RL	1			
				Window w	inder RR	1			
				Rear view r		1			
				Radio (basi		1			
Road Condition	ns During Test Drive	Dry	CD (basic t		1				
Engine Timing		Timing Chain		Number of keys 1		l			
		Central loc		•					
Evidence of Cam Belt Replacement Yes No Kms  Inspected by: Vasanthakumar Mayilswamy						<b>'</b>			
inspected by:	v asammakumal N	Remote lo	Ling	_		<u> </u>			

I have read and understood this condition guide:

Inspection Date: 17 Dec 2025

Published by:

NAME

Vasanthakumar Mayilswamy

SIGNATURE

Sat. nav. (basic test only)

Reversing camera