

•	Report ID:	27,846,633	Version:	1
	Created:	15 Dec 2025		

		Posi	a Condition Cuida	Report ID:	27,846,633	Ve	rsion:	1	
	urner	S Dasi	c Condition Guide	Created:	15 Dec 2025				
Make:	Nissan	Model:	Note				Requir	res	
Body Style:	Hatchback	Year:	2005		OK	Attenti		N/A	
Rego No.:	LPQ459	Rego Expiry:	21 Feb 2026	Engine					
WoF Expiry:	30 Oct 2026	Odometer:	155,807 Kms	Oil level		/			
Good No.:	27846633	VIN:	7AT0DH79X18020891	Smoke & fumes		/			
			No	Engine performance		/			
Next Service: 163000   Service History: No					Noise				
This report is a guide	only. Consideration is mad	le for age and mileage. P	arts have not been dismantled or	Coolant co	ndition	/			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling performance				
Key			-	Radiator / H	<b>/</b>				
-	= Rust	Crack * = Deca	ls W = Significant scuffs	Transmissi	ion				
D = Dent P	T = Paint defect P = P	Pin dent SC = Sto	ne Chips	Operation		<b>/</b>			
SC		SD S	S	Noise		<b>/</b>			
		30 3		Clutch					<b>/</b>
				CV joints		1			
	TA UT			Wheel bea	rings	1			
s sc				Brakes					
	M 11.			Performan	ce	<b>/</b>		П	
			S SC	Hand brake	2	1			
SC	18 VIII			Tyres (lowest observed tread depth of tyres)					
				Left front 4.0 mm					
/	SPT				Right front 5.0 mm				.0 mm
				Left rear 4.			.0 mm		
D SC	W	D S	WSP	Right rear 4.0			.0 mm		
Note: some defects and blemishes may not be displayed in the diagram				Spare Yes					
	on Comments			Suspension					
L/R Bumper Reflector missing, Rust in Boot Floor , R/H Sill Dent.				-	n performance	V			
				Steering pe	·	1			
				Shock abso		1			
Conditions During Body Inspection Dry					Air Conditioning / Heater				
	ge and Under Bonnet	t Inspection Comm		Operation			·	П	
_	oody of Vehicle.	•		Electrical / Accessories					
				Head lights		V		T	
				Tail lights		1			
Interior Comments				Indicators		1		$\dashv$	
Seats: Average				warning lights	1		$\dashv$		
Carpets:	Average			Wipers (fro		1		$\dashv$	
Panels:	Average		-		1		$\dashv$		
Dashboard:	-			Window winder FR				$\dashv$	
General Comments					Window winder RL			_	
Air con not cold ,					inder RR	1		$\dashv$	
, 55 500 y					IIIGEI IIII	-	-	-	

interior comments				
Seats:	Average			
Carpets:	Average			
Panels:	Average			
Dashboard:	Good			
Community Community				

## $\ \, \text{Air con not cold} \;,$

Road Condition	s During Test Drive	Dry
Engine Timing I	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Chris Buckley	
Published by:	Liam Walls	
Inspection Date:	10 Dec 2025	

I have read and understood			
this condition guide:	NAME	SIGNATI	JRE

Rear view mirrors

Number of keys

Central locking Remote locking

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

•

1

1