

Report ID:	27,846,861	Version:	1
Created:	13 Dec 2025		

U	ntuer	S Basi	c Condition Guide
Make:	Hyundai	Model:	130
Body Style:	Hatchback	Year:	2016
Rego No.:	KEC711	Rego Expiry:	14 May 2026
WoF Expiry:	22 Dec 2026	Odometer:	68,307 Kms
Good No.:	27846861	VIN:	KMHD351HMHU349708
Next Service:	80000	Service History:	No
liagnostic testing un	only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
Кеу			
	= Rust $C=C$	rack *= Deca	ls W = Significant scuffs
D = Dent PT	Γ = Paint defect $P = Pi$	in dent SC = Sto	ne Chips
SPSC		SP SP	S
	$\overline{}$		
	-100-		S
s sc 1			
-300 H	A		
	Mr = II		S
S P SC			
			SP
S P		S P S P	SP
lote: some defects	and blemishes may not be	displayed in the diagra	m
Body Inspection	on Comments		
Conditions Dur	ing Body Inspection		Dry
Under Carriag	e and Under Bonnet	Inspection Comm	ents
Interior Comm	ients		
Seats:	Average		
Carpets:	Average		
Panels:	Average		
Dashboard:	Average		

	OK	Requires Attention	
Engine	- OK	According	14//1
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	V		
Cooling performance	/		
Radiator / Hoses (visual)	_		
Transmission		L	
Operation	/	1	
Noise	_		
Clutch			
CV joints	1		
Wheel bearings	1		
Brakes		l	
Performance	/		
Hand brake	7		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	Сригог		5.5 mm
Right front			5.0 mm
Left rear			1.0 mm
Right rear			1.0 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V		
Tail lights	·		
Indicators	·		
Dashboard warning lights	·		
Wipers (front & rear)	·	-	
Window winder FL			
Window winder FR	V	-	
Window winder RL	·	-	
Window winder RR	1		
Rear view mirrors	~		
Radio (basic test only)	<i>'</i>		
CD (basic test only)			
Number of keys	2	<u> </u>	
Central locking	<i>'</i>	1	
Remote locking			
Sat. nav. (basic test only)			
Reversing camera	<i>J</i>	-	
neversing carriera		<u>I</u>	

Inspection Date:	13 Dec 2025
I have read and ui this condition gui	

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Darren Beban

James Scott

Engine Timing Mechanism

Inspected by:

Published by:

Dry

Timing Chain

Yes

NAME		

No

Kms

SIGNATURE		