

Basic Condition Guide

•	Report ID:	27,848,112	Version:	2
	Created:	17 Dec 2025		

	Ulliel			Created: 17 Dec 2025				
Make:	BMW	Model:	5281			Requires		
Body Style:	Wagon	Year:	2014		OK	Attention	N/A	
Rego No.:	QPL173	Rego Expiry:	09 Feb 2026	Engine		<u> </u>		
WoF Expiry:	12 Nov 2026	Odometer:	106,426 Kms	Oil level	-			
Good No.:	27848112	VIN:	WBA5G52020D181331	Smoke & fumes	/		ļ	
Next Service:	116, 512 Kms	Service History:	No	Engine performance	/			
Note: This report is	<u> </u>	Service History.	Noise					
This report is a guide	only. Consideration is mad		Coolant condition					
	ndertaken. The vehicle has l ection prior to purchase ar		Cooling performance	-				
Key			Radiator / Hoses (visual)	V		<u> </u>		
•	= Rust $C=0$	Crack *= Deca	Transmission					
D = Dent P	T = Paint defect P = F	Operation	-		<u> </u>			
		sc	Noise	-				
	$\overline{}$			Clutch			~	
	(M)-			CV joints	'			
		+		Wheel bearings	/			
SC				Brakes				
\mathcal{A}				Performance	-			
11				Hand brake	/			
SC				Tyres (lowest observed tread depth of tyres)				
				Left front		3	3.0 mn	
			(Q)	Right front		3	3.5 mn	
	\angle			Left rear	3.0 mm			
sc		P	Right rear		3	3.0 mn		
Note: some defects	and blemishes may not be	e displayed in the diagra	am	Spare	N/A			
Body Inspecti	on Comments			Suspension				
	nstead of spare whee	el.		Suspension performance	V			
RH skirt scratch	ned.			Steering performance	1			
				Shock absorbers	1			
Conditions Du	ring Body Inspection			Air Conditioning / Heater				
Under Carriag	e and Under Bonne	t Inspection Comn	Operation	V				
			Electrical / Accessories					
				Head lights	V			
				Tail lights	-			
Interior Comn	nents			Indicators	-			
Seats:	Good	- ,		Dashboard warning lights	-			
Carpets:	Good			Wipers (front & rear)	-			
Panels:	Good, ash tray lid broken.			Window winder FL	-			
Dashboard: Good				Window winder FR	1			
General Com	ments		Window winder RL					
				Window winder RR	1			
				Rear view mirrors	1			
				Radio (basic test only)	1			
Road Condition	ns During Test Drive	CD (basic test only)	1					
		Number of keys	2	<u> </u>				
Engine Timing Mechanism Timing Chain Evidence of Cam Belt Replacement Yes			No Kms	Central locking	1			
Evidence of Cam Belt Replacement Yes No Kms				central locking		I	1	

I have read and understood this condition guide:

Inspection Date: 09 Dec 2025

Inspected by:

Published by:

Troy Smith

Shanna Bullion

NAME

SIGNATURE

Remote locking

Reversing camera

Sat. nav. (basic test only)

1