

•	Report ID: 27,850,162		Version:	1
	Created:	16 Dec 2025		


		ОК	Requires Attention	N/A
	Engine			
	Oil level	/		
	Smoke & fumes	<b>/</b>		
1	Engine performance	<b>/</b>		
	Noise	<b>'</b>		
	Coolant condition	V		
ds a	Cooling performance	1		
	Radiator / Hoses (visual)	V		
uffs	Transmission			
	Operation	<b>/</b>		
	Noise	/		
	Clutch			1
	CV joints	1		
	Wheel bearings	1		
	Brakes			
$\overline{}$	Performance	V		
	Hand brake	1		
	Tyres (lowest observed tread	depth of	tvres)	.4 mm
	Left front			3.4 mr
	Right front			res)  8.4 mm 8.2 mm 8.0 mm
	Left rear			
	Right rear			
	Spare	Yes		
	Suspension			
	Suspension performance	· ·		.4 mm
	Steering performance	1		
	Shock absorbers	<b>'</b>		
	Air Conditioning / Heater			
		· ·		
	Operation  Electrical / Accessories			
			<u> </u>	
	Head lights	7		8.4 mm 8.2 mm 8.0 mm
	Tail lights	-		
	Indicators	<b>/</b>		
	Dashboard warning lights	<b>/</b>		
	Wipers (front & rear)	<b>/</b>		
	Window winder FL	/		
	Window winder FR	<b>/</b>		
	Window winder RL	/		
	Window winder RR	/		8.2 mm
	Rear view mirrors	<b>/</b>		
	Radio (basic test only)	•		
	CD (basic test only)	<b>'</b>		
	Number of keys	2		
(ms	Central locking	•		
	Remote locking	/		
	Sat. nav. (basic test only)	<b>'</b>		
	Reversing camera	V		

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2017
Rego No.:	PYU756	Rego Expiry:	31 Dec 2025
WoF Expiry:	30 Dec 2026	Odometer:	123,323 Kms
Good No.:	27850162	VIN:	MNAUM2F50HW727191
Next Service:	133300	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recomme full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

\* = DecalsW = SignificantS = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### **Body Inspection Comments**

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			
4WD			

Interior Comments		
Seats:	Stain on front left seat. Slight wear on drivers	
Carpets:	Drivers side average	
Panels:	Average	
Dashboard:	Fusebox cover panel missing	
General Comments		

## Two key remotes, one doesn't work in ignition

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Malcolm Thomas	•
Inspection Date:	12 Dec 2025	

I have read and understood
this condition guide:

NAME			