

Basic Condition Guida

•	Report ID:	27,850,209	Version:	2	
	Created:	10 Dec 2025			

	umei		— Gorialilon Guide	Created:	10 Dec 2025				
Make:	Honda	Model:	FIT			ОК	Requires Attention	N/A	
Body Style:	Hatchback	Year:	2014	Engine		OK	Attention	IN/A	
Rego No.:	MGQ220	Rego Expiry:	18 Nov 2026	Oil level		V			
WoF Expiry: 24 Dec 2026		Odometer:	144,919 Kms	Smoke & fu	umes	1			
Good No.:	27850209	VIN:	7AT08G2YX19241433	Engine per		1		\vdash	
Next Service:	149197 Kms	Service History:	No	Noise	Torritance	1		 	
Note: This report is		Coolant co	ndition	1					
This report is a guide diagnostic testing u	e only. Consideration is mac ndertaken. The vehicle has l	le for age and mileage. P been driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a		erformance	1			
full mechanical insp	pection prior to purchase ar	nd this can be arranged f 	or an additional charge.		Hoses (visual)	1			
Key		5 I * 5		Transmiss	• • •		<u> </u>		
	R = Rust $C = CPT = Paint defect$ $P = R$	Crack * = Deca Pin dent SC = Sto	Is W = Significant scuffs ne Chips	Operation		V		Т	
D-DCIR 1			nic Criips	Noise		1		\vdash	
		S PSC	Clutch				·		
				CV joints		1		+	
	$\mathcal{O}_{\mathcal{C}}$		(O) s	Wheel bea	rinas	1		 	
S				Brakes	95	-		1	
	19 1			Performan	ice	V	<u> </u>	Т	
				Hand brak	e	1		 	
P SC	HO			Tyres (lowest observed tread depth of tyres)					
()	THE OF			Left front				5.1 mn	
/			(Q)	Right front	t			5.3 mn	
				Left rear			-	3.5 mn	
	S	W	SP	Right rear		4.7 mm			
Note: some defects	s and blemishes may not b	e displayed in the diagra	am	Spare		N/A			
	ion Comments	. , , , , ,		Suspensio	Suspension				
· · · · · · · · · · · · · · · · · · ·				Suspensio	n performance	~			
				Steering p	erformance	1			
				Shock abso	orbers	1			
Conditions Du	iring Body Inspection		Dry	Air Condit	tioning / Heater				
Under Carria	ge and Under Bonne	t Inspection Comm	nents	Operation			V		
Front upper an	d lower Cross Membe	ers have surface rus	t. Engine is tappy when cold.	Electrical	/ Accessories				
				Head light	S	~			
				Tail lights		~			
Interior Com	ments			Indicators		~			
Seats:	Good			Dashboard	d warning lights	~			
Carpets:	Good			Wipers (fro	ont & rear)	~			
Panels:	Good			Window w	rinder FL	~			
Dashboard: Good					vinder FR	~			
General Com	ments		Window w	rinder RL	~				
Air Con not wo	rking. Push button key	y broken.	Window w	rinder RR	/				
				Rear view	mirrors	/			
				Radio (bas	ic test only)	/			
Road Conditions During Test Drive Dry					est only)			1	

I have read and understood this condition guide:

Inspection Date: 10 Dec 2025

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Chris McQuade

Chris McQuade

NAME

No

Timing Chain

Yes

SIGNATURE

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

2

1

1