

•	Report ID: 27,850,284		Version:	1
	Created:	15 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	1		
Engine performance	\( \frac{1}{2} \)		
Noise	1		
Coolant condition			
Cooling performance	1		
Radiator / Hoses (visual)			
Transmission		<u> </u>	
Operation	V		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	J		
Hand brake	1	-	
	denth of	tures)	
Tyres (lowest observed tread of Left front	lepth of		5.0 mm
Right front			5.0 mm
Left rear		-	3.0 mm
Right rear			2.0 mn
Spare	Yes		
Suspension			
Suspension performance		/	
Steering performance		1	
	<b>/</b>		
Shock absorbers	1		
Shock absorbers  Air Conditioning / Heater	<i>V</i>		
Shock absorbers  Air Conditioning / Heater  Operation	\(\frac{1}{V}\)		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories	<i>V</i>		
Shock absorbers  Air Conditioning / Heater  Operation	\( \tau \)		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories		<i>'</i>	
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights	V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights	<i>V</i>	<i>'</i>	
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators	<i>V</i>	<i>V</i>	
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights	V V V V V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)	V V V V V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR	V V V V V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RL  Window winder RR	V V V V V V V V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RR  Rear view mirrors	V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RR  Rear view mirrors  Radio (basic test only)	V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RR  Rear view mirrors  Radio (basic test only)  CD (basic test only)	V V V V V V V V V V V V V V V V V V V		
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RR  Rear view mirrors  Radio (basic test only)  CD (basic test only)  Number of keys	V		✓
Shock absorbers  Air Conditioning / Heater  Operation  Electrical / Accessories  Head lights  Tail lights  Indicators  Dashboard warning lights  Wipers (front & rear)  Window winder FL  Window winder FR  Window winder RR  Rear view mirrors  Radio (basic test only)  CD (basic test only)  Number of keys  Central locking	V		


Make:	Suzuki	Model:	Swift
Body Style:	Hatchback	Year:	2009
Rego No.:	LSY816	Rego Expiry:	28 Apr 2026
WoF Expiry:	29 Apr 2026	Odometer:	141,547 Kms
Good No.:	27850284	VIN:	7AT0GK0CX18555298
Next Service:	144,000	Service History:	Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Kev

itcy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Headlights faded. Windscreen has stone chip. Paint peeling off front of bonnet/has been sprayed poorly (over spray on grille)

Conditions During Body Inspection Dry	Under Carriage and Under Bonnet Inspection Commo	ents
	Conditions During Body Inspection	Dry

Coolant expansion bottle (none pressurized) has no lid.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

RR rego lamp inoperative. Knocking from front over bumps.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by: Finlay Lemmens		
Published by: Luke Saunders		
Inspection Date: 10 Dec 2025		

П	nave	read	and	unde	rstood
tł	nis co	nditi	on a	uide	

NAME			