

Basic Condition Guide

Report ID:	27,850,722	Version:	1
Created:	13 Dec 2025		

Make:	Subaru	Model:	XV	
Body Style:	Hatchback	Year:	2012	
Rego No.: PUG485		Rego Expiry:	09 Sep 2025	
3		Odometer:	166,645 Kms	
WoF Expiry: 24 Sep 2026		VIN:	7AT0GF1XX22024723	
Good No.: 27850722 Next Service: 173,668 kms		Service History:	No	
liagnostic testing ur	only. Consideration is made	een driven up to 50km/h	orts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.	
Кеу				
S = Scratch R	= Rust $C = C$	rack *= Deca	ls W = Significant scuffs	
D = Dent P	$\Gamma = Paint defect P = Paint defect$	in dent SC = Stor	ne Chips	
Body Inspecti	and blemishes may not be on Comments age, rear differential be			
Body Inspecti L tail light dama	on Comments age, rear differential b		ont tyre low.	
Body Inspecti L tail light dama Conditions Dui	on Comments	ushes leak, both fro	ont tyre low.	
Body Inspecti L tail light dama Conditions Dui Under Carriag	on Comments age, rear differential be ring Body Inspection are and Under Bonnet	ushes leak, both fro	ont tyre low.	
Body Inspecti L tail light dama Conditions Dui Under Carriag Interior Comn Seats:	on Comments age, rear differential be ring Body Inspection are and Under Bonnet hents Average	ushes leak, both fro	ont tyre low.	
Endy Inspection Land Land Land Land Land Land Land Lan	on Comments age, rear differential be ring Body Inspection are and Under Bonnet nents Average Average	ushes leak, both fro	ont tyre low.	
Endy Inspection Land Land Land Land Land Land Land Lan	ring Body Inspection e and Under Bonnet Average Average Average Average	ushes leak, both fro	ont tyre low.	
Endy Inspection Land Land Land Land Land Land Land Lan	nents Average Average Average Average Average Average Average	ushes leak, both fro	ont tyre low.	
Conditions Dur Under Carriag Interior Comn Seats: Carpets: Panels: Dashboard:	nents Average Average Average Average Average Average Average	ushes leak, both fro	Dry eents	
Example 1	ing Body Inspection le and Under Bonnet Average Average Average Average Average on, fuse box coin poor	Inspection Comm	Dry eents	
Endy Inspection L tail light dama Conditions Dur Under Carriag Interior Comm Seats: Carpets: Panels: Dashboard: General Comm Dashboard light	nents Average	ushes leak, both fro	Dry eents	

,		D=							
	ОК	Requires Attention	N	/A					
Engine									
Oil level		V							
Smoke & fumes	1								
Engine performance	•								
Noise	/								
Coolant condition	1								
Cooling performance	•								
Radiator / Hoses (visual)	1								
Transmission									
Operation	/								
Noise	/								
Clutch				V					
CV joints	~								
Wheel bearings	1								
Brakes									
Performance	•								
Hand brake	1								
Tyres (lowest observed tread d	epth of	tyres)							
Left front			2	mm					
Right front			2	mm					
Left rear			3	mm					
Right rear			3	mm					
Spare	N/A								
Suspension									
Suspension performance	1								
Steering performance	1								
Shock absorbers	~								
Air Conditioning / Heater									
Operation	1								
Electrical / Accessories									
Head lights	/								
Tail lights		~							
Indicators	1								
Dashboard warning lights		~							
Wipers (front & rear)		~							
Window winder FL	1								
Window winder FR	1								
Window winder RL	1								
Window winder RR	•								
Rear view mirrors	1								
Radio (basic test only)	1								
CD (basic test only)	•								
Number of keys	1								
Central locking	1								
Remote locking	1								
Sat. nav. (basic test only)				~					
Reversing camera	1								
-									

I have read and understood this condition guide:

Inspection Date: 13 Dec 2025

Inspected by:
Published by:

NAME

Marlon Espena

Marlon Espena

SIGNATURE