


Make:	Subaru	Model:	Exiga
Body Style:	Wagon	Year:	2008
Rego No.:	NFN547	Rego Expiry:	05 Mar 2026
WoF Expiry:	23 Jan 2027	Odometer:	125,828 Kms
Good No.:	27851464	VIN:	7AT0GF1RX20006173
Next Service:	135800	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	wear
Carpets:	wear holes
Panels:	scratches, marks
Dashboard:	Good

General Comments

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Cambelt		
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	95,843 Kms
Inspected by:	Melissa Wilson		
Published by:	Melissa Wilson		
Inspection Date:	09 Jan 2026		

I have read and understood
this condition guide:

NAME

SIGNATURE