


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Mazda | Model: | Premacy |
| Body Style: | Wagon | Year: | 2009 |
| Rego No.: | NBA284 | Rego Expiry: | |
| WoF Expiry: | 09 Jan 2026 | Odometer: | 211,857 Kms |
| Good No.: | 27851527 | VIN: | 7AT0C133X20336671 |
| Next Service: | | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor stonechips on windscreen

Conditions During Body Inspection

Dry

Under Carriage and Under Bonnet Inspection Comments

Front wheel drive

Oil leak

Interior Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

General Comments

Due for service

Static in radio

Has no rear view mirror

Only a black screen for the reverse camera

Road Conditions During Test Drive

Dry

Engine Timing Mechanism

Timing Chain

Evidence of Cam Belt Replacement

☐ Yes

☐ No

Kms

Inspected by: Cameron Senior-Arnold

Published by: Janine Bell

Inspection Date: 11 Dec 2025

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,851,527 | Version: | 1 |
| Created: | 19 Dec 2025 | | |

| | OK | Requires Attention | N/A |
|---|----|--------------------|--------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | | ✓ | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 3.6 mm |
| Right front | | | 3.9 mm |
| Left rear | | | 3.6 mm |
| Right rear | | | 4.0 mm |
| Spare | | No | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | | ✓ | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | | | ✓ |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | ✓ | |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____