

## **Basic Condition Guide**

Report ID:	27,852,226	Version:	1
Created:	19 Dec 2025		

	oniei				Created:	19 Dec 2025
Make:	Holden	Model:	Cruze			
Body Style: Sedan		Year:	2012		Engine	
Rego No.:	GES310	Rego Expiry:	30 Jul 2026		Oil level	
WoF Expiry:	25 Jan 2026	Odometer:	107,036 Kms		Smoke & fumes	
Good No.:	27852226	VIN:	6G1PD5EY2CL6	23844		
Next Service: 117000 Service History: No			No	No Engine performance No Noise		
Note: This report is	not a warranty				Coolant co	ndition
This report is a guide diagnostic testing un	only. Consideration is made dertaken. The vehicle has b	e for age and mileage. Pa een driven up to 50km/h	arts have not been disman n from cold. The Vendor re	tled or commends a	Cooling pe	
	ection prior to purchase and				31	Hoses (visual)
Key					Transmiss	
	= Rust $C = C$ $\Gamma$ = Paint defect $P = Pi$			ificant scuffs	Operation	1011
D=Defit P1	r = Paint delect P = Pi	11 dent 3C = 3toi	ie Chips		Noise	
sc	W	sc		D SC	Clutch	
	$\sim$		$(\bigcirc)$	S SC	CV joints	win as
		<u> </u>			Wheel bea Brakes	iligs
M			All	/	Performan	60
1				SC	Hand brake	
SDSC	65 1				Tyres (lowest observed tr	
2020		$\longrightarrow$			Left front	
				S		
					Right front Left rear	
SC	W	SC			Right rear	
					Spare	
Body Inspection	and blemishes may not be	displayed in the diagra	m		Suspensio	an .
, -	t window screen				-	n performance
Ctorio omp nom	Wildow Colocii				•	erformance
					Shock abso	
Conditions Dur	ing Pady Inspection		Wet			
	ing Body Inspection e and Under Bonnet	Inspection Comm				ioning / Heater
Onder Carriag	e and Onder Bonnet	inspection comm	ents		Operation	/ A
						Accessories
					Head lights	>
lataria Caran					Tail lights	
Interior Comm	1				Indicators	La contra de Pada La
Seats:	wear, marks					l warning lights
Carpets:	Good				Wipers (fro	
Panels:	Good				Window w	
Dashboard:	Good				Window w	
General Comn	nents				Window w	
					Window w	
					Rear view r	nirrors

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	/		
Engine performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Noise	~		
Coolant condition	1		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation	<b>/</b>		
Noise	1		
Clutch			~
CV joints	1		
Wheel bearings	~		
Brakes	1		
Performance	/		
Hand brake	1		
Tyres (lowest observed tread d	lepth of	tyres)	
Left front			5 mm
Right front			6 mm
Left rear			7 mm
Right rear			7 mm
Spare	Yes		
Suspension			
Suspension performance	·		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	·	l	
Electrical / Accessories			
Head lights	1	l	1
	<b>/</b>		
Tail lights Indicators	1		
	1		
Dashboard warning lights  Winors (front & roor)	<b>V</b>	-	
Wipers (front & rear) Window winder FL	1	-	
	1	-	
Window winder FR	1		
Window winder RL		-	
Window winder RR	<b>V</b>	-	
Rear view mirrors	<b>/</b>	-	
Radio (basic test only)	<b>/</b>	-	
CD (basic test only)	1		L
Number of keys	1	ı	1
Central locking	/		
Remote locking	<b>/</b>		
Sat. nav. (basic test only)			
Reversing camera		ļ	

have read and understood
his condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 19 Dec 2025

Melissa Wilson

Melissa Wilson

Engine Timing Mechanism

Inspected by:

Published by:

N.	ΔΜ	F

Wet

Timing Chain

No

Yes

S	IGI	N A	TI	JR	F

Kms