


Make:	Mini	Model:	Cooper
Body Style:	Hatchback	Year:	2010
Rego No.:	NKC185	Rego Expiry:	14 Sep 2025
WoF Expiry:	11 Jul 2026	Odometer:	98,528 Kms
Good No.:	27853731	VIN:	WMWSU32010TY96378
Next Service:		Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Engine oil leak

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		<input type="checkbox"/> Yes	<input type="checkbox"/> No
Inspected by:	Sione Mae		
Published by:	Sione Mae		
Inspection Date:	13 Dec 2025		

NAME _____

SIGNATURE