

•	Report ID:	27,853,881	Version:	1
	Created:	12 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	~		
Transmission			
Operation	/		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			3.4 mm
Right front		3	3.9 mm
Left rear			1.2 mm
Right rear		3	3.8 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	/		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	1		
Rear view mirrors	/		
Radio (basic test only)		·	
CD (basic test only)			
Number of keys	1		
Central locking	1		
Remote locking	/		
Sat. nav. (basic test only)			1
Reversing camera			1
J			

Make:	Nissan	Model:	Bluebird
Body Style:	Sedan	Year:	2006
Rego No.:	HRE799	Rego Expiry:	05 Jan 2026
WoF Expiry:	15 Sep 2026	Odometer:	253,506 Kms
Good No.:	27853881	VIN:	7AT0DH1EX14023307
Next Service:	15/3/26	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Minor stonechips on windscreen

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Front wheel drive

Oil leak

Transmission leak

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	bubbles in dash-Average	
General Comments		

Radio has no audio

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Cameron Senior-Arnold		
Published by:	Janine Bell		
Inspection Date:	12 Dec 2025		

have read and understood
this condition quide

NAME			