

Report ID:	27,853,997	Version:	1
Created:	19 Dec 2025		

Basic Condition Guide			Created: 19 Dec 20		rision; I			
Make:	Toyota	Model:	Hiace		ОК	Requires Attention	N/A	
Body Style:	Van	Year:	2009	Engine	OK.	Attention	IN/A	
Rego No.:	RAY423	Rego Expiry:	20 Mar 2026	Oil level	· ·		1	
WoF Expiry:	21 Mar 2026	Odometer:	356,885 Kms	Smoke & fumes	V			
Good No.:	27853997	VIN:	JTFHT02P900035731	Engine performance				
Next Service:	365000	Service History:	No	Noise				
	is not a warranty			Coolant condition			1	
agnostic testing ι	le only. Consideration is mad undertaken. The vehicle has	been driven up to 50km	Cooling performance			1		
	pection prior to purchase a	nd this can be arranged	Tor an additional charge.	Radiator / Hoses (visual)				
≘y = Scratch Ⅰ	R = Rust C = 0	Crack *=Dec	als W = Significant scuffs	Transmission				
	PT = Paint defect P = I		one Chips	Operation	V			
		•		Noise	· ·			
		* *		Clutch		1		
				CV joints			1	
	TO ST			Wheel bearings	V			
-				Brakes				
	1191			Performance		V		
			R	Hand brake	V			
* SC	HR JL			Tyres (lowest observed tread depth of tyres)				
				Left front		5.0 n		
			Right front		5.0 m			
The state of the s				Left rear		5.0 m		
				Right rear		5.0		
ote: some defect	s and blemishes may not b	e displayed in the diag	ram	Spare	Yes	Yes		
Body Inspect	tion Comments			Suspension	,			
				Suspension performance	ce 🗸			
				Steering performance	·			
				Shock absorbers	V			
Conditions Du	uring Body Inspection		Dry	Air Conditioning / Hea	ter			
	ge and Under Bonne			Operation	V			
	ke hose needs refitting	g, rubbing on calipe	er	Electrical / Accessories				
il around turb	00			Head lights	V			
			Tail lights	V				
Interior Comments			Indicators	V				
Seats:	eats: worn, stained		Dashboard warning ligh	nts 🗸				
Carpets:	worn		Wipers (front & rear)	V				
Panels: missing/ damaged		Window winder FL	V					
Dashboard: Good			Window winder FR	V				
General Comments				Window winder RL			~	
				Window winder RR			/	
				Rear view mirrors	V			
				Radio (basic test only)	/			

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	336,000 Kms
Inspected by:	Greg Morgan			
Published by:	Stuart Manson			
Inspection Date:	11 Dec 2025			

I have read and understood this condition guide:

NAME			

SIGNATURE			

2

1

•

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera