

Report ID:	27,854,669	Version:	4
Created:	17 Dec 2025		

	ntuer	S Basi	c Condition Guide
Make:	Honda	Model:	Jazz
Body Style:	Hatchback	Year:	2005
Rego No.:	CSF49	Rego Expiry:	30 Jun 2026
WoF Expiry:	23 Jul 2026	Odometer:	147,481 Kms
Good No.:	27854669	VIN:	JHMGD18305S252456
Next Service:	154,400kms	Service History:	No
diagnostic testing un	only. Consideration is made	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.
Кеу			
S = Scratch R	= Rust $C=C$	:rack *= Deca	ls W = Significant scuff
D = Dent P	$\Gamma = Paint defect  P = P$	in dent SC = Sto	ne Chips
		D	
$\overline{}$			
	(D)=		SC
SC (			
P SC			
			PT
	S	P	
	and blemishes may not be on Comments	displayed in the diagra	am
body mapeed	on comments		
Conditions Dur	ring Body Inspection		Dry
	e and Under Bonnet	Inspection Comm	
onaci camay	e and onder bonnet	spection comi	icito
Interior Comm	nents		
ciioi coilili	ICIIC		

		Requires	
	OK	Attention	N/A
Engine			
Oil level	•		
Smoke & fumes	V		
Engine performance	<b>'</b>		
Noise	<b>V</b>		
Coolant condition	1		
Cooling performance	•		
Radiator / Hoses (visual)	<b>'</b>		
Transmission			
Operation	•		
Noise	•		
Clutch			V
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	•		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		-	7.0 mm
Right front			7.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	1		
Shock absorbers	/		
Air Conditioning / Heater	<u> </u>		<u> </u>
Operation	<b>/</b>		
Electrical / Accessories			l
Head lights	<b>/</b>		
Tail lights	/		
Indicators	1		
Dashboard warning lights	/		
Wipers (front & rear)	1		
Window winder FL	<b>'</b>		
Window winder FR	<i>'</i>		
Window winder RL	<b>'</b>		<u> </u>
Window winder RR	<i>'</i>		<u> </u>
Rear view mirrors	<b>'</b>		
Radio (basic test only)	<b>'</b>		
	<i>y</i>		
CD (basic test only)	2		<u> </u>
Number of keys	<i>y</i>		
Central locking	.,		
Remote locking	<b>V</b>		
Sat. nav. (basic test only)			<u> </u>
Reversing camera			V

Road Conditions During Test Drive		Dry		
Engine Timing N	Mechanism	Timing Chain		
Evidence of Can	n Belt Replacement	Yes	No	Kms
Inspected by:	LukaAjitvan Woerden			
Published by:	Cody O'Neill			
Increaction Date:	13 Dec 2025			

I have read and understood this condition guide:

Good

Good

Good

Good

Seats:

Carpets:

Panels: Dashboard:

**General Comments** 

NAME

SIGNATURE