

•	Report ID: 27,855,259		Version:	2
	Created:	12 Dec 2025		

	ntuet	B asi	c Condition Guide				_	
	offici			Created:	12 Dec 2025			
Make:	Ford	Model:	Fiesta				Requires	
Body Style:	Hatchback	Year:	2016	Engine		OK	Attention	N/A
Rego No.:	KEC793	Rego Expiry:	22 Nov 2026	Oil level		V		
WoF Expiry:	03 Dec 2026	Odometer:	105,554 Kms	Smoke & fu	ımos	1		
Good No.:	27855259	VIN:	MPB8XXMXJ8GY56910			1		
Next Service:	115,500 Kms	Service History:	No	Engine per	Tormance	1		-
lote: This report is	not a warranty	•		Noise Coolant co	ndition	1		
his report is a guide	e only. Consideration is mad	e for age and mileage. P	arts have not been dismantled or h from cold. The Vendor recommends a			1		
	ection prior to purchase an			Cooling pe		<i>'</i>		
Кеу					Hoses (visual)			
	= Rust C = C			Transmiss	ion			
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation				
D SC	S	T SC PT SC	SC SC	Noise				
$\overline{}$				Clutch		<u>.</u>		/
			S	CV joints		/		
SC				Wheel bearings				
T A	18			Brakes			ı	
			P	Performan	ce	/		<u> </u>
				Hand brake	2	/		
P SC				Tyres (lowest observed tread depth of tyres)				
			SC	Left front				4.5 mn
				Right front				4.5 mn
				Left rear	t rear 4.0 r			4.0 mn
SC	<u>s</u>	PSP	D P	Right rear 6.5 m			3.5 mn	
lote: some defects	and blemishes may not be	e displayed in the diagra	am	Spare		Yes		
Body Inspecti	on Comments			Suspensio	n			
RR reflector cracked. LH sill scuffed.				Suspension	n performance	/		
				Steering pe	erformance	/		
				Shock abso	orbers	/		
Conditions Du	ring Body Inspection			Air Condit	ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
Engine oil leak.				Electrical / Accessories				
				Head light:	5	/		
				Tail lights		/		
Interior Comn	nents			Indicators		~		
Seats:	Poor, hole in drivers seat back.			Dashboard	warning lights	1		
Carpets:	Good			Wipers (fro	nt & rear)	~		
Panels: Good			Window w	inder FL	1			
Dashboard:	poard: Good			Window w	inder FR	1		
General Comments					inder RL	1		
				Window w	inder RR	1		
				Rear view r	nirrors	1		
						4		1

		_		
Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Troy Smith			
Published by:	Tony Yiu			
Inspection Date:	11 Dec 2025			

SIGNATURE		

1 2

1

•

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

Number of keys

Central locking Remote locking

I have read	and	und	erstood
this condit	ion g	guide	2: