

Basic Condition Guide

•	Report ID: 27,855,341		Version:	1
	Created:	18 Dec 2025		

mm mm mm

		Rag	sic Condition Guide	21,000,011			
	ntuet	<u> </u>		Created: 18 Dec 2025			
Make:	Nissan	Model:	Pulsar		01/	Requires	
Body Style:	Hatchback	Year:	2005	Engine	OK	Attention	N,
Rego No.:	EZC699	Rego Expiry:		Oil level			
WoF Expiry:	01 Aug 2025	Odometer:	141,383 Kms	Smoke & fumes	1		-
Good No.:	27855341	VIN:	SJNFBAN16A0554381	Engine performance	1		\vdash
Next Service:	19/7/25	Service History:	No	Noise	V		
lote: This report i	s not a warranty			Coolant condition	1		\vdash
nis report is a guid	e only. Consideration is made Indertaken. The vehicle has b	e for age and mileage. been driven up to 50km	Parts have not been dismantled or n/h from cold. The Vendor recommends a	Cooling performance	-		-
ıll mechanical insp	pection prior to purchase an	d this can be arranged	for an additional charge.	Radiator / Hoses (visual)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		-
ey				Transmission			
	R = Rust C = C				· ·	T T	Т
) = Dent F	PT = Paint defect P = P	in dent SC = St	one Chips	Operation	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		┢
S SC	W	S SC SC	WS	Noise			┝
				Clutch	/		┢
	\sim		S SC	CV joints	<i>\</i>		⊢
S SC				Wheel bearings	/		
	118			Brakes		T	
			SC	Performance	-		┝
][Hand brake	/		
S SC				Tyres (lowest observed tread	depth of		
`			SSC	Left front			5.6
				Right front			4.2
s	W	SC S	WSSC	Left rear	5.8		-
		30 3		Right rear			5.4
	s and blemishes may not be	displayed in the diag	ram	Spare	Yes		
	tion Comments			Suspension			
Minor stonech	ips on windscreen			Suspension performance	/		L
				Steering performance	/		L
				Shock absorbers	/		L
Conditions Du	uring Body Inspection		Dry	Air Conditioning / Heater			
Under Carria	ge and Under Bonnet	Inspection Com	ments	Operation	/		L
Front wheel dri Oil leak	ive			Electrical / Accessories			
Oil leak Rear left ball jo	oint leaking			Head lights	/		
				Tail lights	/		
Interior Com	ments			Indicators	/		L
Seats:	Good			Dashboard warning lights	/		
Carpets:	Good	Good			/		
Panels:	Good			Window winder FL	/		
Dashboard:	Good			Window winder FR	/		
General Comments				Window winder RL	/		
Due for service since 19/7/25				Window winder RR	/		
Needs rego Both left side windows only work with drivers button				Rear view mirrors	V		
. San lott blub V	work with	Dattori		Radio (basic test only)	~		
Road Condition	ons During Test Drive	Dry		CD (basic test only)			
		-: · OI ·					_

I have read and understood
this condition guide:

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 12 Dec 2025

Janine Bell

Cameron Senior-Arnold

NAME		

No

Timing Chain

Yes

SIGNATURE	

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

1

1

1