

Report ID:	27,856,083	Version:	5
Created:	19 Dec 2025		

	nuer	S Basi	c Condition Guide	
Make:	MG	Model:	ZS	
Body Style: SUV Rego No.: RNH263		Year:	2022	
		Rego Expiry:	02 Aug 2026	
WoF Expiry:	30 Dec 2026	Odometer:	22,745 Kms	
Good No.:	27856083	VIN:	LSJW74U93NZ070065	
Next Service:	29,000 kms	Service History:	No	
diagnostic testing und ull mechanical inspe	only. Consideration is made	een driven up to 50km/ł	orts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.	
<b>(ey</b> S = Scratch R =	= Rust C = C	rack * = Deca	ls W = Significant scuffs	
	= Paint defect $P = Pi$		3	
		D D		
$\overline{}$				
			(Q)	
lote: some defects a	and blemishes may not be	displayed in the diagra	m	
Body Inspection				
Conditions Duri	ng Body Inspection		Dry	
	e and Under Bonnet	Inspection Comm		
onder carriage	e una oriaci pormet	mspection comm	iches -	
Interior Comm	ents			
Seats:	Good			
Carpets:	Good			
Panels:	Good			

	OK	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	1		
Engine performance			
Noise	\( \tau \)		
Coolant condition	1		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission		l	
Operation	<b>V</b>		
Noise	<i>y</i>		
Clutch			
	•		<u> </u>
CV joints			
Wheel bearings			
Brakes			
Performance	/		
Hand brake			
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7 mm
Right front			7 mm
Left rear			6 mm
Right rear			6 mm
Spare	Yes		
Suspension			
Suspension performance	•		
Steering performance	<b>/</b>		
Shock absorbers	/		
Air Conditioning / Heater			•
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	1		
Tail lights	1		
Indicators			
Dashboard warning lights	<b>V</b>		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	·		<u> </u>
Rear view mirrors	<i>'</i>		<del>                                     </del>
Radio (basic test only)	<i>'</i>		
			_
CD (basic test only)	2	<u> </u>	
Number of keys		1	<u> </u>
Central locking	<i>'</i>		
Remote locking	<b>'</b>		
Sat. nav. (basic test only)  Reversing camera	•		

Road Condition	s During Test Drive	Dry	
Engine Timing N	Mechanism	Timing Chain	
Evidence of Can	n Belt Replacement	Replacement Yes No Kms	
Inspected by:	Marlon Espena		
Published by:	Marlon Espena		
Inspection Date:	19 Dec 2025		
Inspection Date:	19 Dec 2025		

have read and understood
this condition quide

Good

Dashboard:

**General Comments** 

N	Δ	M	F	

SIGNATURE