

•	Report ID:	27,856,199	Version:	2
	Created:	12 Dec 2025		


	ОК	Requires Attention	N/A
Engine	<u> </u>		,
Oil level	V		
Smoke & fumes	/		
Engine performance			
Noise			
Coolant condition			
Cooling performance	✓		
Radiator / Hoses (visual)	·		
Transmission			
Operation			
Noise	_		
Clutch	V		
CV joints			
Wheel bearings			
Brakes	•		
Performance	J		
Hand brake	<u> </u>		
	onth of	turos)	
Tyres (lowest observed tread d Left front	еритог	tyres)	7 mm
Right front Left rear			
Right rear	Yes		2 mm
Spare	res		
Suspension		Ι	
Suspension performance			
Steering performance			
Shock absorbers			
Air Conditioning / Heater			
Operation		<i>'</i>	
Electrical / Accessories		I	Г
Head lights			
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	/		
Window winder RL			
Window winder RR			
Rear view mirrors			
Radio (basic test only)	/		
CD (basic test only)	•		
Number of keys	2		
Central locking	•		
Remote locking			
Sat. nav. (basic test only)			'
Reversing camera			V

Make:	Ford	Model:	Transit
Body Style:	Van	Year:	2000
Rego No.:	NPP799	Rego Expiry:	05 Jul 2026
WoF Expiry:	28 Nov 2026	Odometer:	334,118 Kms
Good No.:	27856199	VIN:	WF0LXXGBFLYC36014
Next Service:	337,682kms	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Headlight lenses dull.

Rust in rear door shut, front door steps, right A pillar r/f wheel arch.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Engine oil leaks.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
	-	

General Comments

A/C works, but fan only works on high.

Rusty areas around vehicle, further inspection suggested.

5 speed manual diesel Transit camper van.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Daryll Timms	
Published by:	Daryll Timms	
Inspection Date:	12 Dec 2025	

I have read and	understood
this condition a	uida

NAME			