

## **Basic Condition Guide**

Report ID:	27,856,467	Version:	1	
Created:	18 Dec 2025			

	Ulliel	<u> </u>		Created:	18 Dec 2025				
Make:	Honda	Model:	Accord			011	Requires		
Body Style:	Sedan	Year:	2007	Fu ain a		OK	Attention	N/A	
Rego No.:	PPD763	Rego Expiry:	31 Jan 2026	Engine				l	
WoF Expiry:	05 Aug 2026	Odometer:	261,164 Kms	Oil level		<u> </u>			
Good No.:	27856467	VIN:	7AT08G13X14303629	Smoke & fumes					
Next Service:		Service History:	Engine performance						
lote: This report is	s not a warranty		Noise  Coolant condition						
his report is a guide liagnostic testing u	e only. Consideration is mad Indertaken. The vehicle has	de for age and mileage. I been driven up to 50km			<u> </u>				
	pection prior to purchase ar			erformance					
Cey			Radiator / Hoses (visual)  Transmission						
S = Scratch R = Rust C = Crack *= Decals W = Significant scuffs D = Dent PT = Paint defect P = Pin dent SC = Stone Chips								Г	
D = Dent P	71 = Paint defect P = F	711 dent	one Cnips	Operation					
S		s sc s sc	SSC	Noise Clutch					
	(0)		S SC	CV joints Wheel bea	rings				
S SC		<u> </u>		Brakes	anngs				
			AHY	Performar	200			Π	
			sc	Hand brak					
SDSC	Hot						tvres)		
3030				Left front	Tyres (lowest observed tread depth of tyres)  Left front 2.2 mr				
			SSC	Right from	t			6.5 m	
				Left rear		4.9 mm			
S SC	W :	S SC S SC	SSC	Right rear				5.7 m	
lote: some defects	s and blemishes may not b	e displayed in the diag	Spare		Yes				
	ion Comments	e displayed in the diagi	an	Suspension					
Minor crack/sto	onechips on windscre	en		Suspensio	n performance	V			
				-	erformance	<b>V</b>			
				Shock abs	orbers	<b>/</b>			
Conditions Du	uring Body Inspection		Air Condi	tioning / Heater					
Conditions During Body Inspection Dry  Under Carriage and Under Bonnet Inspection Comments					ı		<b>/</b>		
Front wheel dri			Electrical / Accessories						
Couldn't inspec	ct underbody because	car is to low for th	e hoist	Head light	ts		<b>/</b>		
				Tail lights		<b>/</b>			
Interior Com	ments			Indicators		<b>/</b>			
Seats:	Good			Dashboard	d warning lights	<b>/</b>			
Carpets:	Good		Wipers (fro	ont & rear)	<b>V</b>				
Panels:	Good		Window w	vinder FL	/				
Dashboard: Good					vinder FR	<b>✓</b>			
General Com	ments			Window w	vinder RL	/			
Due for service					vinder RR	<b>/</b>			
				Rear view	mirrors	<b>/</b>			
A C HOT COID	dlight not working								
VC HOT COID	dlight not working			Radio (bas	sic test only)	•			
	dlight not working	Dry		Radio (bas		✓ 		V	
	ons During Test Drive	Dry Timing Chain			test only)	1		~	
Road Conditio	ons During Test Drive	-	No Kms	CD (basic t	test only) f keys			<i>'</i>	
Engine Timing	ons During Test Drive g Mechanism am Belt Replacement	Timing Chain  Yes	No Kms	CD (basic t	test only) f keys cking	1		✓ <b>✓</b>	

I have read and understood this condition guide:

Inspection Date: 13 Dec 2025

NAME \_\_

SIGNATURE

Reversing camera