

Basic Condition Guide


•	Report ID:	27,857,949	Version:	1
	Created:	12 Dec 2025		

	ОК	Requires Attention	N/A
Engine	<u> </u>	Attention	14/74
Oil level	1		
Smoke & fumes	1		
Engine performance	V		
Noise	/		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission	-	ı	
Operation	/		
Noise	1		
Clutch			
CV joints	1		
Wheel bearings	1		
Brakes	1		
Performance	V		
Hand brake	1		
Tyres (lowest observed tread d	lepth of	tyres)	
Left front			1.0 mm
Right front		3	3.4 mm
Left rear			1.6 mm
Right rear			1.8 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	,	•	
Operation	~		
Electrical / Accessories	,		
Head lights	1		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	~		
Window winder FR	1		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera			~
			'

Make:	Honda	Model:	Insight	
Body Style:	Hatchback	Year:	2011	
Rego No.: FSB447		Rego Expiry:	26 Jul 2026	
WoF Expiry: 17 May 2026		Odometer:	218,704 Kms	
Good No.: 27857949		VIN:	JHMZE2850BS204477	
Next Service:	220,149 Kms	Service History:	No	

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chip in front windscreen

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			
2WD			

Interior Comments

	Seats:	Stains. Wear on drivers seat		
Carpets: Average				
Panels: Scuffs on boot lid panel		Scuffs on boot lid panel		
	Dashboard:	Good		

General Comments

Rear window tint bubbling

Two key remotes, one isn't working

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by: Hoani Saunders		
Published by: Miroslav Granich		
Inspection Date:	12 Dec 2025	

I have read and understood
this condition guide:

NAME			

ς	IG	N	ΔT	ш	RI	F