

Basic Condition Guide

Report ID:	27,858,531	Version:	1	
Created:	15 Dec 2025			

U	ntue	S Basi	c Condition Guide	Created: 15 Dec 2025			
Make:	Ford	Model:	Escape		04	Requires	NI/A
Body Style:	SUV	Year:	2003	Engine	OK	Attention	N/A
Rego No.:	FBS565	Rego Expiry:	22 Jan 2026	Oil level	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
WoF Expiry:	09 Jan 2026	Odometer:	214,872 Kms	Smoke & fumes	1		
Good No.:	27858531	VIN:	7A86G5D0709102370	Engine performance	1		<u> </u>
Next Service:	221100km	Service History:	No	Noise	1		
Note: This report i	s not a warranty			Coolant condition	1		
diagnostic testing u	ndertaken. The vehicle has b	peen driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling performance	1	<u> </u>	
full mechanical insp	pection prior to purchase an	nd this can be arranged f	or an additional charge.	Radiator / Hoses (visual)	1		
Key				Transmission			
	R = Rust C = C PT = Paint defect P = P			Operation	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<u> </u>	
	T = Tailit delect T = T		Noise	1			
		D P		Clutch	+		
				CV joints	1		<u> </u>
	$\mathcal{O}_{\mathcal{F}}$		(O) SD	Wheel bearings	1		
SW (Brakes			
				Performance	/	<u> </u>	
			SPT	Hand brake	1		
SPT	HOS II			Tyres (lowest observed tread depth of tyres)			
371				Left front	черитог	tyles/	5 mm
			SDPT	Right front			6 mm
				Left rear			5 mm
		D SD	S	Right rear			6 mm
Note: some defects and blemishes may not be displayed in the diagram				Spare	Yes		
	ion Comments	e displayed in the diagra	am	Suspension	100		
, .	as two cracks outside t	the CVA.		Suspension performance	·		
Left Tail Light i	s cracked.			Steering performance	1		
	rd Aerial missing. Light glass is cracked.			Shock absorbers	1		
	uring Body Inspection		Dry	Air Conditioning / Heater		l	
	ge and Under Bonnet	t Inspection Comm		Operation Operation			
	ansmission oil seepage		iento	Electrical / Accessories			
Ū	. 0			Head lights		·	
				Tail lights	·		
Interior Com	ments			Indicators	· /		
Seats:	missing rear seat	headrests		Dashboard warning lights	1		
Carpets:	Average			Wipers (front & rear)	1		
Panels:	Average			Window winder FL	1		
Dashboard:	Average			Window winder FR	· /		
General Comments				Window winder RL	1		
4WD.				Window winder RR	1		
				Rear view mirrors	1		
				Radio (basic test only)	1		
Road Condition	ons During Test Drive	Dry		CD (basic test only)	1		
		Timing Chain		Number of keys	1	1	
Engine Timing Mechanism				Number of Reys			

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 15 Dec 2025

Haden Brown

Haden Brown

NAME			

No

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Yes

SIGNATURE

1