

•	Report ID:	27,858,614	Version:	2
	Created:	16 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	✓ ✓		
Noise	/		
Coolant condition	/		
Cooling performance	~		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	V		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			4 mm
Right front			4 mm
Left rear			6 mm
Right rear			6 mm
Spare	N/A		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		•	
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	1		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	2		
Central locking	1		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	1		


Make:	Mazda	Model:	CX-5
Body Style:	Wagon	Year:	2014
Rego No.:	MTU936	Rego Expiry:	01 Jun 2026
WoF Expiry:	20 Feb 2026	Odometer:	146,227 Kms
Good No.:	27858614	VIN:	7AT0C144X20117408
Next Service:	over due	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

1/	

* = Decals W = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Windscreen stone chip cracked

FL fog lamp not glowing

Headlights faded

Tyre mobility kit available

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Fwd

Interior Comments			
Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
General Comments			
RL room lamp not glowing			

Tailgate pull handle missing Steering wheel infotainment controls not working

FL rear view mirror control not working

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by: Vasanthakumar M		<i>l</i> layilswamy	
Published by:	Vasanthakumar M	Mayilswamy	
Inspection Date: 16 Dec 2025			

П	nave	read	and	unde	rstood
tł	nis co	nditi	on a	uide	

NAME			

GNA	\TU	IRF		