

•	Report ID:	Report ID: 27,859,462		1	
	Created:	16 Dec 2025			

		Doo:	a Candition Cuida	ricport ib.	21,000,402	\ VC	131011.	
	ntuet	S Dasi	c Condition Guide	Created:	16 Dec 2025			
Make:	Toyota	Model:	Markx				Requires	
Body Style:	Wagon	Year:	2011	Engine		OK	Attention	N/A
Rego No.:	REL639			Engine				1
WoF Expiry:			Oil level Smoke & fu		7		-	
Good No.:	27859462	VIN:	7AT0H64TX24043627			•   -		
Next Service:	can't read	Service History:	No	Engine per Noise	Tormance	<b>V</b>		
Note: This report is	Note: This report is not a warranty					V		-
This report is a guide	only. Consideration is mad	e for age and mileage. Pa	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling no		1	-	-
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.	Cooling pe		1		
Key					Hoses (visual)			
	= Rust C = C				Transmission			
D = Dent $P$	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation		1		
	W		W	Noise		-		
				Clutch				<b>/</b>
	(O)=		S	CV joints		<b>/</b>		
				Wheel bea	rings	/	L	
M	18			Brakes			I	
				Performan		/		
				Hand brake		<b>/</b>	L	
(d)				Left front	est observed tread	depth of	tyres)	
						_		7 mm
				Right front		_		7 mm
	W	D	W	Left rear				6 mm
				Right rear		<u> </u>		6 mm
	and blemishes may not be	e displayed in the diagra	am	Spare		Yes		
, ,	on Comments			Suspensio			I	
Driver seat belt	worn, L inner tail ligh	t cracked ,r fog ligh	t not working,	-	n performance	/		
					erformance	/		
			Τ_	Shock abso		/		
	ring Body Inspection		Dry		ioning / Heater			
Under Carriage and Under Bonnet Inspection Comments				Operation		/		
					Accessories		ı	
				Head light:	S	/		
				Tail lights		/		
Interior Comments				Indicators		/		
Seats: Average				l warning lights	/		<u> </u>	
Carpets: Average			Wipers (fro		/			
Panels: Average			Window w	inder FL	/			
Dashboard: Good			Window w	inder FR	<b>/</b>			

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Good	
General Comments		

## Driver body seal torn, driver seat worn,

Pood Condition	s During Test Drive	Dry
noad Condition	S During lest Drive	ыу
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	16 Dec 2025	

I have read and understood			
this condition quide:	NAME	CIGNATURE	

Window winder RL

Window winder RR

Rear view mirrors

Number of keys

Central locking Remote locking

Radio (basic test only) CD (basic test only)

Sat. nav. (basic test only) Reversing camera

1

1

1

1 1

1

•