


•	Report ID: 27,859,539		Version:	1
	Created:	18 Dec 2025		

	ОК	Requires Attention	N/A
Engine			-
Oil level	/		
Smoke & fumes	1		
Engine performance			
Noise	/		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission		l	
Operation	1		
Noise	1		
Clutch			
CV joints	1		
Wheel bearings	1		
Brakes		1	
Performance	V	I	
Hand brake	1		
Tyres (lowest observed tread d	enth of	tyres)	
Left front	eptiroi	•	3.5 mm
Right front			
Left rear			3.8 mm
Right rear	V		1.2 mm
Spare	Yes		
Suspension		I	
Suspension performance	•		
Steering performance			
Shock absorbers			
Air Conditioning / Heater		I	
Operation	/		
Electrical / Accessories	Ι	Ι.	
Head lights			
Tail lights			
Indicators	/		
Dashboard warning lights	1		
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Wipers (front & rear)	V V		
	V V V		
Wipers (front & rear)	\(\times \)		
Wipers (front & rear) Window winder FL	V V V		
Wipers (front & rear) Window winder FL Window winder FR	\(\times \)		
Wipers (front & rear) Window winder FL Window winder FR Window winder RL	\(\times \)		
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	V V V V V V V		
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	V V V V V V V	· · · · · · · · · · · · · · · · · · ·	
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	V V V V V V V	V	
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	\(\times \) \(\t	· · · · · · · · · · · · · · · · · · ·	
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\(\text{\chi} \) \(\ch	<i>'</i>	
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\text{\chi} \) \(\ch	V	

Make:	Mazda	Model:	Axela
Body Style:	Hatchback	Year:	2006
Rego No.:	HMY903	Rego Expiry:	28 Feb 2026
WoF Expiry:		Odometer:	185,238 Kms
Good No.:	27859539	VIN:	7AT0C13JX14222386
Next Service:	15/8/25	Service History:	No
diagnostic testing und	only. Consideration is made	een driven up to 50km/h	orts have not been dismantled or I from cold. The Vendor recommends a or an additional charge.

ĸ	ΔV
-11	C۷

S = Scratch R = RustC = Crack* = DecalsW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Minor stonechips on windscreen

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Front wheel drive

Interior Comments

Oil leak

Seats:	Good			
Carpets:	Good			
Panels:	Good			
Dashboard:	Good			
General Comm	ients			
Due for service since 15/8/25 Due for wof Left front park light not working Radio can't find radio station				
Road Conditions During Test Drive Engine Timing Mechanism		Timing Chain		
Evidence of Can	n Belt Replacement	Yes No Kms		
Inspected by: Cameron Senior-Arnold				
Published by:	Janine Bell			
Inspection Date:	16 Dec 2025			

I have read and understood
this condition guide:

NAME			

SIGNATURE		