

Basic Condition Guida

Report ID:	27,860,184	Version:	1	
Created:	16 Dec 2025			

	nue			Created: 16 Dec 2025			
Make:	Mazda	Model:	Demio			Requires Attention	N/A
Body Style:	Hatchback	Year:	2012	Engine OK Attent		Attention	14//1
Rego No.:	LAR396	Rego Expiry:	17 Jan 2026	Oil level			
WoF Expiry:	03 Nov 2026	Odometer:	197,814 Kms	Smoke & fumes			
Good No.:	27860184	VIN:	7AT0C12HX17515007	Engine performance	1		
Next Service:	189,000 Kms	Service History:	No	Noise	1		
lote: This report i	•	Coolant condition	1				
iagnostic testing u	e only. Consideration is mad Indertaken. The vehicle has b	Cooling performance	V				
	pection prior to purchase an	nd this can be arranged	Radiator / Hoses (visual)	V			
Key S - Seratch				Transmission			
S = Scratch $R = Rust$ $C = Crack$ *= Decals W = Significant scuffs $D = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$ $D = PT = P$				Operation	V		
				Noise	V		
				Clutch			
				CV joints			
		+	SSC	Wheel bearings			
\longrightarrow 6				Brakes			
	119/			Performance	V		
			S	Hand brake			
PT SC	HA	<u>/</u>		Tyres (lowest observed tread depth of tyres)			
				Left front 3.1 mi			
			(Q)	Right front	4.1 m		
D W P SC Note: some defects and blemishes may not be displayed in the diagram				Left rear		4.1 m	
				Right rear	5.1 m		5.1 mr
				Spare	Yes	Yes	
Body Inspect	ion Comments			Suspension			
•	ront windscreen			Suspension performance	·		
Front bumper I	loose on right side			Steering performance	·		
				Shock absorbers	·		
Conditions Du	ıring Body Inspection		Wet	Air Conditioning / Heater			
Under Carria	ge and Under Bonnet	t Inspection Com	nents	Operation	V		
2WD				Electrical / Accessories			
Surface rust in	engine bay and on un	derside of vehicle		Head lights	V		
				Tail lights	V		
Interior Comments			Indicators	V			
Seats:	Average. Stains.	ns. Front seat covers fitted		Dashboard warning lights			
Carpets:	Average	ge		Wipers (front & rear)	~		
Panels:	Average. Paint spilled in boot area			Window winder FL	· ·		
Dashboard: Average				Window winder FR	· ·		
General Comments				Window winder RL	·		
				Window winder RR	·		
				Rear view mirrors	~		
				Radio (basic test only)	V		
Road Condition	ons During Test Drive	Wet		CD (basic test only)	~		
						-	

I have read and understood this condition guide:

Inspection Date: 16 Dec 2025

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Hoani Saunders

Miroslav Granich

NAME			

No

Timing Chain

Yes

SIGNATURE		

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

2

1