

Report ID:	27,860,431	Version:	3
Created:	22 Dec 2025		

	urner	S Basi	ic Condition Guide	Created: 22 D
Make:	Mazda	Model:	Axela	
Body Style:	Hatchback	Year:	2017	
Rego No.:	RDA827	Rego Expiry:	27 Dec 2025	Engine
WoF Expiry:	31 Dec 2026	Odometer:	123,490 Kms	Oil level
Good No.:	27860431	VIN:	7AT0C13JX24200957	Smoke & fumes
Next Service:	133,495kms	Service History:	No	Engine performa
	,	Service History.	110	Noise
Note: This report is This report is a guide	only. Consideration is mad	e for age and mileage. P	arts have not been dismantled or	Coolant condition
diagnostic testing ur full mechanical insp	ndertaken. The vehicle has b ection prior to purchase an	een driven up to 50km/ d this can be arranged f	h from cold. The Vendor recommends a for an additional charge.	Cooling perform
Key				Radiator / Hoses
•	= Rust $C=C$	Crack *= Deca	N = Significant scuffs	Transmission
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation
Р			S	Noise
		\top		Clutch
				CV joints
	MA UN			Wheel bearings
SC				Brakes
	MC 11			Performance
				Hand brake
SC	18 VI			Tyres (lowest ob
				Left front
			(Q)	Right front
				Left rear
	S		S	Right rear
Note: some defects	and blemishes may not be	e displayed in the diagra	am	Spare
Body Inspecti	on Comments			Suspension
Tire repair kit ir	stead of spare.			Suspension perfe
				Steering perform
				Shock absorbers
Conditions Du	ring Body Inspection		Dry	Air Conditionin
Under Carriag	ge and Under Bonnet	: Inspection Comm	nents	Operation
		. · ·		Electrical / Acce
				Head lights
				Tail lights
Interior Comn	nents			Indicators
Seats:	Good			Dashboard warn
Carpets:	Good			Wipers (front & r
Panels:	Good			Window winder
Dashboard:	Good			Window winder
General Com				Window winder
Jeneral Collin				Window winder
				Rear view mirror

		Requires	
	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	•		
Engine performance	-		
Noise	/		
Coolant condition	•		
Cooling performance	•		
Radiator / Hoses (visual)	•		
Transmission		Γ	
Operation	•		
Noise	•		
Clutch			
CV joints	•		
Wheel bearings			
Brakes		ı	
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of		
Left front		-	1.0 mm
Right front			5.0 mm
Left rear			1.5 mm
Right rear			5.0 mm
Spare	N/A		
Suspension		ı	
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		ı	
Operation	/		
Electrical / Accessories		1	
Head lights	•		
Tail lights	•		
Indicators	•		
Dashboard warning lights	•		
Wipers (front & rear)	•		
Window winder FL	V		
Window winder FR	'		
Window winder RL	'		
Window winder RR	•		
Rear view mirrors	•		
Radio (basic test only)	•		
CD (basic test only)	•		
Number of keys	1		
Central locking	•		
Remote locking	•		
Sat. nav. (basic test only)			~
Reversing camera	/		

Road Condition	s During Test Drive	Dry
Engine Timing N	Mechanism	Timing Chain
Evidence of Can	n Belt Replacement	Yes No Kms
Inspected by:	LukaAjitvan Woer	rden
Published by:	Cody O'Neill	
Inspection Date:	16 Dec 2025	
		'

I have read and understood this condition guide:

NΔ	

SIGNATURE