

Basic Condition Guide

Report ID:	27,860,477	Version:	1
Created:	15 Dec 2025		

	ulle		Sic Condition Galae	Created:	15 Dec 2025				
	1_						Poguiros		
Make:	Toyota	Model:	Caldina			ОК	Requires Attention	N/A	
Body Style:	SUV	Year:	2003	Engine					
Rego No.:	FDU369	Rego Expiry:	03 Aug 2026	Oil level		•			
WoF Expiry:	02 Mar 2026	Odometer:	235,446 Kms	Smoke & fumes		•			
Good No.: 27860477 VIN: 7A8H6240709009565 Next Service: 230,000km Service History: No				Engine performance					
Next Service:	· ·	Service History:	Noise		/				
ote: This report is nis report is a guide	only Consideration is ma	ide for age and mileage.	Coolant co	ondition		•			
iagnostic testing ur ıll mechanical insp	ndertaken. The vehicle has ection prior to purchase a	s been driven up to 50kn and this can be arranged	Cooling pe	erformance	/				
ey	1	1	Radiator / Hoses (visual)		/				
-	= Rust C =	Crack *= Dec	cals W = Significant scuffs	Transmission					
D = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$						•			
S SC	W	SRW SDW	WSDW	Noise		/			
$\overline{}$		\top		Clutch				~	
	- 60		S PT SC W	CV joints		/			
S SC W				Wheel bearings		/			
330 W	19			Brakes					
			S SC	Performan	ice	/			
				Hand brak	e	/			
SC W	18			Tyres (lowest observed tread depth of tyres)					
				Left front		3		3 m	
			SRW	Right front	t			2 m	
			WSRW	Left rear		5 mn			
SDW		SDW SDW	Right rear		5		5 m		
lote: some defects	and blemishes may not b	oe displayed in the diag	ram	Spare Yes					
Body Inspecti	on Comments			Suspension	on				
Windscreen sto	ne chips			Suspensio	n performance	/			
Boot rust				Steering p	erformance	/			
				Shock abs	orbers	•			
Conditions Du	ring Body Inspection	<u> </u>	Dry	Air Conditioning / Heater					
Under Carriag	e and Under Bonne	et Inspection Com	ments	Operation 🗸					
No coolant	a ail la al-a			Electrical	/ Accessories				
Excessive engir Underbody surf			Head light	S	/				
Front wheel driv				Tail lights 🗸		/			
Interior Comn	nents			Indicators		•			
Seats:	Average		Dashboard	d warning lights	/				
Carpets:	Poor				ont & rear)	•			
Panels:	Average			Window w	rinder FL	/			
Dashboard:	Average		Window w	rinder FR	/				
General Comr	ments			Window w	rinder RL	/			
			_	Window w	rinder RR	/			
				Rear view	mirrors	•			
				Radio (bas	ic test only)	/			
Road Condition	ns During Test Drive	Dry	CD (basic t	est only)	•				
Engine Timing	Mechanism	Timing Chain	Number of	fkeys	2				
Evidence of Ca	m Belt Replacement	Yes	No Kms	Central loc	king		'		
Inspected by:	Rowan Fey			Remote lo	cking		~		
Published by: Rowan Fey				Sat. nav. (b	pasic test only)			~	
, , , , , , , , , , , , , , , , , , ,							1		

I have read and understood this condition guide:

Inspection Date: 15 Dec 2025

NAME

SIGNATURE

Reversing camera