

Report ID:	27,860,939	Version:	2
Created:	15 Dec 2025		

ca Ti	ntuet	Basi	c Condition Guide	•	27,000,939	VC	131011.		
	oniei			Created:	15 Dec 2025				
Make:	Nissan	Model:	Murano				Requires		
Body Style:	Wagon	Year:	2005	Facility			Attention	N/A	
Rego No.:	KKA737	Rego Expiry:	10 Aug 2026	Engine					
WoF Expiry:	21 Feb 2026	Odometer:	109,715 Kms	Oil level		·	<b>/</b>		
Good No.:	27860939	VIN:	7AT0DH74X17004400			<u> </u>			
Next Service:	112,000kms	Service History:	No	Engine per	formance	/			
Note: This report is	not a warranty	,	110130		<i>'</i>				
	e only. Consideration is mad ndertaken. The vehicle has b	Coolain contains		<i>'</i>					
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.		erformance	/			
Key				Radiator / Hoses (visual)					
	= Rust $C = C$			Transmission					
D = Dent P	T = Paint defect P = P	Operation		/		İ			
	P.	Noise		/					
		Clutch				-			
		CV joints		/					
				Wheel bearings					
-	18			Brakes					
$\mathcal{A}$	M = 1	$\mathbb{N} - \mathbb{I}$		Performan	ce	/			
				Hand brake	e	/			
P				Tyres (lowest observed tread depth of tyres)					
		Left front		4 m		4 mm			
				Right front		4		4 mm	
	-			Left rear				6 mm	
	S	S P SC W	SC W	Right rear				6 mm	
Note: some defects	and blemishes may not be	e displayed in the diagra	nm	Spare Yes					
Body Inspecti	ion Comments			Suspensio	n				
	ch up on window frame			Suspension	n performance	/			
Hatch door not Bonnet struts n	opening, further investigation	stigation needed.		Steering performance		/			
Dominor strate in	icca replacing.			Shock abso	orbers	1			
Conditions Du	ring Body Inspection	Air Conditioning / Heater							
Under Carriag	ge and Under Bonnet	Operation		~					
Engine oil leak.		Electrical / Accessories							
				Head light:	S	1			
				Tail lights		1			
Interior Comm	nents	Indicators		1					
Seats:	Drivers seat rip or	Dashboard	l warning lights	1					
Carpets:	Average				ont & rear)	1			
Panels: Cargo blind missing.					inder FL	1			
Dashboard: Steering wheel worn.					inder FR	1			
General Com		Window w		1					
	ngine / transmission, s	suggest mounts.	Window w		1				
2WD petrol auto		50	Rear view r		1				
				ricui vicvi i		. •		1	

Road Conditions During Test Drive Dry Timing Chain Engine Timing Mechanism Evidence of Cam Belt Replacement Yes No Kms Inspected by: **Daryll Timms** Published by: **Daryll Timms** 15 Dec 2025 Inspection Date:

NAME

SIGNATURE

1

1

1

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)