

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Left front wing mirror indicator lens broken
Windscreen edges delaminating and bottom rubber perished

Front Wheel Drive
Minor engine oil leak
Tyres are getting low

Seats:	Average
Carpets:	Poor
Panels:	Average
Dashboard:	Average

Existing fault codes are active
Master Switch buttons are broken

I have read and understood
this condition guide:

NAME _____

SIGNATURE

	OK	Requires Attention	N/A
--	----	-----------------------	-----

Spare	Yes
-------	-----

Reversing camera			✓
------------------	--	--	---