

•	Report ID:	27,862,349	Version:	1
	Created:	19 Dec 2025		

ОК

Requires Attention

N/A

		Poci	a Candition Guida	Report ID: 27,862,349
Basic Condition Guide		Created: 19 Dec 2025		
	1		0	
Make:	Toyota	Model:	Corolla	
Body Style:	Wagon	Year:	2017	Engine
Rego No.:	KNB5	Rego Expiry:	20 Aug 2025	Oil level
NoF Expiry:	17 Dec 2026	Odometer:	151,957 Kms	Smoke & fumes
Good No.:	27862349	VIN:	JTDZE4GEX01000907	Engine performance
lext Service:	162,000	Service History:	Yes	Noise
ote: This report is not a warranty his report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or				Coolant condition
agnostic testing ur	ndertaken. The vehicle has be ection prior to purchase an	een driven up to 50km/l	n from cold. The Vendor recommends a	Cooling performance
•	- Prior to parcriase ari	a and can be arranged i	- an additional charge.	Radiator / Hoses (visual)
ey = Scratch R	= Rust	rack *= Deca	ls W = Significant scuffs	Transmission
	T = Paint defect P = P		3	Operation
D.00	10/			Noise
P SC	W	S	S SC	Clutch
S P SC				CV joints
				Wheel bearings
SC W				Brakes
SC				Performance
				Hand brake
				Tyres (lowest observed tread
				Left front
			(Q)	Right front
				Left rear
S D	W	P	W P	Right rear
lote: some defects and blemishes may not be displayed in the diagram			Spare	
Body Inspection Comments			Suspension	
				Suspension performance
				Steering performance
				Shock absorbers
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater
Jnder Carriag	je and Under Bonnet	Inspection Comm	nents	Operation
WD				Electrical / Accessories
				Head lights

Oli level				
Smoke & fumes	/			
Engine performance	\(\)			
Noise	/			
Coolant condition	V			
Cooling performance	'			
Radiator / Hoses (visual)	/			
Transmission				
Operation	/			
Noise	'			
Clutch			/	
CV joints	/			
Wheel bearings	/			
Brakes				
Performance	'			
Hand brake	/			
Tyres (lowest observed tread	depth of	tyres)		
Left front		6	6.4 mm	
Right front		(3.5 mm	
Left rear		Ę	5.2 mm	
Right rear		Ę	5.2 mm	
Spare	Yes			
Suspension				
Suspension performance	/			
Steering performance	'			
Shock absorbers	/			
Air Conditioning / Heater				
Operation	/			
Electrical / Accessories				
Head lights	'			
Tail lights	/			
Indicators	/			
Dashboard warning lights	/			
Wipers (front & rear)	/			
Window winder FL	'			
Window winder FR	/			
Window winder RL	/			
Window winder RR	/			
Rear view mirrors	/			
Radio (basic test only)	1			
CD (basic test only)	V			
Number of keys	1			
Central locking	'			
Remote locking	'			
Sat. nav. (basic test only)			V	
Reversing camera			'	

Interior Comments		
Seats:	Stains on front left seat, slight wear on drivers	
Carpets:	Wear on drivers side	
Panels:	Scuffs on boot lid panel	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Miroslav Granich	
Inspection Date:	18 Dec 2025	

I have read and understood
this condition guide:

NAME	

SI	GN	AT	URF	