


## **Basic Condition Guide**

•	Report ID:	27,862,775	Version:	4
	Created:	24 Dec 2025		

Subaru	Model:	Legacy
Wagon	Year:	2010
PER141	Rego Expiry:	30 Sep 2025
18 Dec 2026	Odometer:	211,213 Kms
27862775	VIN:	7AT0GF0BX21022055
222,000 kms	Service History:	No
	Wagon PER141 18 Dec 2026 27862775	Wagon         Year:           PER141         Rego Expiry:           18 Dec 2026         Odometer:           27862775         VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

ney				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

### **Body Inspection Comments**

Front bumper loose, needs refitting properly. Left headlight washer nozzle cover missing.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments		
Seats:	Average	
Carpets:	Hole worn on drivers side.	
Panels:	Console lid & drivers door panel wrinkled.	
Dashboard:	Average	

# **General Comments**

AWD petrol Legacy wagon.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	98,166 Kms
Inspected by:	Daryll Timms			
Published by:	Leon Sun			
Inspection Date:	15 Dec 2025			

I have read and understood this condition guide: NAME			
this condition guide: NAME	I have read and understood		
	this condition guide:	NAME	

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Engine performance	<b>/</b>		
Noise	V V		
Coolant condition	~		
Cooling performance	<b>✓</b>		
Radiator / Hoses (visual)	<b>✓</b>		
Transmission			
Operation	<b>✓</b>		
Noise	/		
Clutch			<b>'</b>
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	~		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		3	3.0 mm
Right front		3	3.0 mm
Left rear		4	1.0 mm
Right rear		ţ	5.0 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	/		
Shock absorbers	<b>✓</b>		
Air Conditioning / Heater			
Operation	<b>✓</b>		
Electrical / Accessories			
Head lights	<b>✓</b>		
Tail lights	<b>/</b>		
Indicators	<b>✓</b>		
Dashboard warning lights	V V		
Wipers (front & rear)	<b>✓</b>		
Window winder FL	<b>V</b>		
Window winder FR			
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	<b>✓</b>		
Number of keys	1		
Central locking	<b>✓</b>		
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera			

SIGNATURE	