


| Report ID: | 27,862,924  | Version: | 2 |
|------------|-------------|----------|---|
| Created:   | 31 Dec 2025 |          |   |

| Make:         | Hyundai     | Model:           | Santa FE          |
|---------------|-------------|------------------|-------------------|
| Body Style:   | SUV         | Year:            | 2020              |
| Rego No.:     | MQQ767      | Rego Expiry:     | 21 Jan 2026       |
| WoF Expiry:   | 13 Jan 2027 | Odometer:        | 82,798 Kms        |
| Good No.:     | 27862924    | VIN:             | KMHS381CSKU150786 |
| Next Service: | 92500       | Service History: | Yes               |

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

| Ney         |                   |              |                  |                        |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust          | C = Crack    | * = Decals       | W = Significant scuffs |
| D = Dent    | PT = Paint defect | P = Pin dent | SC = Stone Chips |                        |



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

| Conditions During Body Inspection                   | Dry |  |  |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments |     |  |  |

All wheel drive/

| Interior Comments |         |  |
|-------------------|---------|--|
| Seats:            | Average |  |
| Carpets:          | Average |  |
| Panels:           | Average |  |
| Dashboard:        | Average |  |
| General Comments  |         |  |

# Come with some service history

| Road Conditions During Test Drive |             | Dry          |
|-----------------------------------|-------------|--------------|
| Engine Timing Mechanism           |             | Timing Chain |
| Evidence of Cam Belt Replacement  |             | Yes No Kms   |
| Inspected by: Bobby Zhong         |             |              |
| Published by: Bobby Zhong         |             |              |
| Inspection Date:                  | 31 Dec 2025 |              |

| I have read and understood |
|----------------------------|
| this condition quido:      |

| NAME |  |  |  |
|------|--|--|--|

|                                | ОК   | Requires<br>Attention | N/A      |
|--------------------------------|--|-----------------------|----------|
| Engine                         |  |                       |          |
| Oil level                      | <b>/</b>   |                       |          |
| Smoke & fumes                  | <b>/</b>   |                       |          |
| Engine performance             | <b>✓</b>   |                       |          |
| Noise                          | \( \text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tince{\tint{\text{\text{\text{\text{\text{\text{\text{\tin}\exitt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\text{\tinit}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\tinit}\\ \text{\texi}\text{\text{\text{\texi}\text{\text{\texi}\text{\text{\texi}\text{\text{\texi}\text{\text{\texi}\til\titt{\text{\texi}\text{\texi{\texi}\text{\texi{\texi{\texi{\texi}\til\tint{\texit{\texi{\texi{\texi}\texi{\texit{\texi{\tex |                       |          |
| Coolant condition              | <b>/</b>   |                       |          |
| Cooling performance            | <b>/</b>   |                       |          |
| Radiator / Hoses (visual)      | <b>/</b>   |                       |          |
| Transmission                   |  | ı                     |          |
| Operation                      | <b>V</b>   |                       |          |
| Noise                          | <b>/</b>   |                       |          |
| Clutch                         |  |                       | V        |
| CV joints                      | <b>/</b>   |                       |          |
| Wheel bearings                 | <b>/</b>   |                       |          |
| Brakes                         |  |                       |          |
| Performance                    | /  |                       |          |
| Hand brake                     | <b>/</b>   |                       |          |
| Tyres (lowest observed tread d | epth of  | tyres)                |          |
| Left front                     | •  |                       | 6 mm     |
| Right front                    |  |                       | 6 mm     |
| Left rear                      |  |                       | 6 mm     |
| Right rear                     |  |                       | 6 mm     |
| Spare                          | Yes  |                       |          |
| Suspension                     |  |                       |          |
| Suspension performance         |  |                       |          |
| Steering performance           | · /  |                       |          |
| Shock absorbers                |  |                       |          |
| Air Conditioning / Heater      |  |                       |          |
| Operation                      |  |                       |          |
| Electrical / Accessories       |  |                       |          |
| Head lights                    |  |                       |          |
| Tail lights                    | <b>/</b>   |                       |          |
| Indicators                     | <b>✓</b>   |                       |          |
| Dashboard warning lights       | <b>✓</b>   |                       |          |
| Wipers (front & rear)          | ·  |                       |          |
| Window winder FL               | ·  |                       |          |
| Window winder FR               |  |                       |          |
| Window winder RL               | ·  |                       |          |
| Window winder RR               | · ·  |                       |          |
| Rear view mirrors              |  |                       |          |
| Radio (basic test only)        | ~  |                       |          |
| CD (basic test only)           | -  |                       |          |
| Number of keys                 | 2  | l                     |          |
| Central locking                |  |                       |          |
| Remote locking                 |  |                       | <u> </u> |
| Sat. nav. (basic test only)    | ·  |                       |          |
| Reversing camera               | · /  |                       |          |
| g carriera                     | -  | <u> </u>              | <b>—</b> |

| SIGNATURE |  |  |  |
|-----------|--|--|--|